District I		, 50	ate of New.Me	exico		Form C-10	
1/053/ 5 1 5 1	The state of the s	Energy M	inerals and Natu	ral Resources	WELL API NO.	October 13, 200	9
District II	Hobbs, NM 88240		IGEDALATION:	DIVIGION	30-025	-09621	
Submit 3 Copies To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88210 District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION District III 1320 South St. Frencis Dr.					5. Indicate Type of		
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505					STATE _	FEE 🛛	
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM HOBBS 87505					6. State Oil & Gas	Lease No. 5443	
	SUNDRY NOTI	CES AND REPO	RTS ON WELLS	}		Unit Agreement Name	,
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					Cooper Jal Unit		
1. Type of Well:		Gas Well 🔲 O	ther /		8. Well Number	206	\Box
2. Name of Operator Resaca Operating Company					9. OGRID Number 263848		
3. Address of Operator					10. Pool name or Wildcat		
	4	St. Suite 1450, He	ouston, TX 77010		Jalmat; Tan	sill-Yates-7Rivers	
4. Well Location						e .	,
Unit Let			rom theNort			— — /	
Section	24	Townshi	<u> </u>	nge 36E	NMPM Lea	County	V V V
		11. Elevation (S	3310' KB	, RKB, RT, GR, etc.			
	12. Check A	Appropriate Bo	x to Indicate N	ature of Notice,	Report or Other I	Data	
N	OTICE OF IN	ITENTION TO	١.	CHE	SEQUENT REP	ODT OE:	
		PLUG AND AB		REMEDIAL WOR		ALTERING CASING	1
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI						P AND A	
PULL OR ALTER	CASING	MULTIPLE CO!	MPL 🗌	CASING/CEMEN	T JOB 🔲		
DOWNHOLE CO	MMINGLE						
OTHER:					an Out Well and Conv		
	proposed or comp					, including estimated da	
of starting				ie Completions. A	nach wendore diagrai	n or proposed complen	2 **
of starting or recomp	g any proposed wo	ork). SEE RULE	r 103. Por Munip	•	-	1 1	on
or recomp	g any proposed wo bletion.	ove Ground Steel	•	•	-		on
or recomp 1.) MIRU Pu 2.) RIH w/ 4	g any proposed wo oletion. Iling Unit and Ab ³ / ₄ " Bit & 6- 3 ½"	ove Ground Steel Drill Collars on 2	Pit. 2/24/11 7/8" work string				on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou	g any proposed wo bletion. Illing Unit and Ab ³ / ₄ " Bit & 6- 3 ½" tt cement and CIB	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti	Pit. 2/24/11 7/8" work string nue in hole clean	, tagged @ 2795'. ing out to 3230'; ci	rculated clean.		on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w/	g any proposed wo bletion. Illing Unit and Ab ³ / ₄ " Bit & 6-3 ½" it cement and CIB (2 7/8" work strin	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and	Pit. 2/24/11 7/8" work string nue in hole clean l bit.		rculated clean.		on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w/ 5.) RIH w/ 2	g any proposed wo bletion. Illing Unit and Ab ³ / ₄ " Bit & 6- 3 ½" at cement and CIB (2 7/8" work strin 3/8" x 5 ½" Arroy	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer	Pit. 2/24/11 7/8" work string nue in hole clean l bit. & set @ 2925'.	ing out to 3230'; ci	rculated clean. ed 15,000#'s rock salt		on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w/ 5.) RIH w/ 2 6.) Acidized 7.) POOH lay	g any proposed wo bletion. Illing Unit and Ab ³ / ₄ " Bit & 6- 3 ½" at cement and CIB ⁷ / ₂ 7/8" work strin ³ /8" x 5 ½" Arrow OH 2983'-3230'v ying down work st	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer v/ 12,000 gallons tring; RIH w/ On/v	Pit. 2/24/11 27/8" work string nue in hole clean bit. \$ set @ 2925'. 15% HCl 90/10 A	ing out to 3230'; ci			on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w/ 5.) RIH w/ 2 6.) Acidized 7.) POOH lay 8.) Performed	g any proposed wo bletion. Iling Unit and Ab ³ / ₄ " Bit & 6- 3 ½" at cement and CIB ¹ / ₂ 7/8" work strin ³ /8" x 5 ½" Arrow OH 2983'-3230'v ying down work stated	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer v/ 12,000 gallons tring; RIH w/ On/chanical Integrity	Pit. 2/24/11 7/8" work string nue in hole clean l bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held.	ing out to 3230'; circid/ Xylene, dropportion string.			on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w/ 5.) RIH w/ 2 6.) Acidized 7.) POOH lay 8.) Performed	g any proposed wo bletion. Iling Unit and Ab ³ / ₄ " Bit & 6- 3 ½" at cement and CIB ¹ / ₂ 7/8" work strin ³ /8" x 5 ½" Arrow OH 2983'-3230'v ying down work stated	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer v/ 12,000 gallons tring; RIH w/ On/v	Pit. 2/24/11 7/8" work string nue in hole clean l bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held.	ing out to 3230'; circid/ Xylene, dropportion string.			on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w/ 5.) RIH w/ 2 6.) Acidized 7.) POOH lay 8.) Performed	g any proposed wo bletion. Illing Unit and Ab 3/4" Bit & 6- 3 ½" at cement and CIB (2 7/8" work strin 3/8" x 5 ½" Arrov OH 2983'-3230'v ying down work si d Preliminary Med ulling Unit, clean	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer w/ 12,000 gallons tring; RIH w/ On/o chanical Integrity location, clean and	Pit. 2/24/11 7/8" work string nue in hole clean l bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held. d dispose of pit fl	cid/ Xylene, droppotion string.	ed 15,000#'s rock salt		on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w/ 5.) RIH w/ 2 6.) Acidized 7.) POOH lay 8.) Performed	g any proposed wo bletion. Iling Unit and Ab ³ / ₄ " Bit & 6- 3 ½" at cement and CIB ¹ / ₂ 7/8" work strin ³ /8" x 5 ½" Arrow OH 2983'-3230'v ying down work stated	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer w/ 12,000 gallons tring; RIH w/ On/o chanical Integrity location, clean and	Pit. 2/24/11 7/8" work string nue in hole clean l bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held.	cid/ Xylene, droppotion string.			on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w/ 5.) RIH w/ 2 6.) Acidized 7.) POOH lay 8.) Performed 9.) RDMO P	g any proposed wo bletion. Illing Unit and Ab 3/4" Bit & 6- 3 ½" at cement and CIB (2 7/8" work strin 3/8" x 5 ½" Arrov OH 2983'-3230'v ying down work si d Preliminary Med ulling Unit, clean	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer w/ 12,000 gallons tring; RIH w/ On/o chanical Integrity location, clean and	Pit. 2/24/11 7/8" work string nue in hole clean l bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held. d dispose of pit fl	cid/ Xylene, droppotion string.	ed 15,000#'s rock salt		on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled or 4.) POOH w/ 5.) RIH w/ 2 6.) Acidized 7.) POOH lay 8.) Performed 9.) RDMO P	g any proposed wo bletion. Illing Unit and Ab ³ / ₄ " Bit & 6- 3 ½" at cement and CIB ¹ / ₂ 7/8" work strin 3/8" x 5 ½" Arrov OH 2983'-3230'v ying down work st d Preliminary Mec ulling Unit, clean	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer w/ 12,000 gallons tring; RIH w/ On/w chanical Integrity location, clean and	Pit. 2/24/11 27/8" work string nue in hole clean bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held. d dispose of pit fl	cid/ Xylene, droppetion string.	ed 15,000#'s rock salt		on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w/ 5.) RIH w/ 2 6.) Acidized 7.) POOH lay 8.) Performed 9.) RDMO P	g any proposed wo bletion. Illing Unit and Ab ³ / ₄ " Bit & 6- 3 ½" at cement and CIB ¹ / ₂ 7/8" work strin 3/8" x 5 ½" Arrov OH 2983'-3230'v ying down work st d Preliminary Mec ulling Unit, clean	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer w/ 12,000 gallons tring; RIH w/ On/w chanical Integrity location, clean and	Pit. 2/24/11 27/8" work string nue in hole clean bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held. d dispose of pit fl	cid/ Xylene, droppetion string.	ed 15,000#'s rock salt		on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w/ 5.) RIH w/ 2 6.) Acidized 7.) POOH lay 8.) Performed 9.) RDMO P Spud Date:	g any proposed wo bletion. Illing Unit and Ab ³ / ₄ " Bit & 6- 3 ½" at cement and CIB ¹ / ₂ 7/8" work strin 3/8" x 5 ½" Arrov OH 2983'-3230'v ying down work st d Preliminary Mec ulling Unit, clean	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer w/ 12,000 gallons tring; RIH w/ On/w chanical Integrity location, clean and	Pit. 2/24/11 27/8" work string nue in hole clean I bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held. d dispose of pit fl Rig Release Da	cid/ Xylene, droppetion string.	ed 15,000#'s rock salt		on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled or 4.) POOH w/ 5.) RIH w/ 2 6.) Acidized 7.) POOH lay 8.) Performed 9.) RDMO P	g any proposed wo bletion. Illing Unit and Ab ³ / ₄ " Bit & 6- 3 ½" at cement and CIB ¹ / ₂ 7/8" work strin 3/8" x 5 ½" Arrov OH 2983'-3230'v ying down work st d Preliminary Mec ulling Unit, clean	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer w/ 12,000 gallons tring; RIH w/ On/w chanical Integrity location, clean and	Pit. 2/24/11 27/8" work string nue in hole clean bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held. d dispose of pit fl	cid/ Xylene, droppetion string.	ed 15,000#'s rock salt 3/2/2011 re and belief.		on
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w/ 5.) RIH w/ 2 6.) Acidized 7.) POOH la 8.) Performed 9.) RDMO P Spud Date:	g any proposed wo bletion. Illing Unit and Ab 3/4" Bit & 6- 3 1/2" at cement and CIB (2 7/8" work strin 3/8" x 5 1/2" Arroy OH 2983'-3230've ying down work string down work string Unit, clean 2/24/20 It the information	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer of 12,000 gallons tring; RIH w/ On/o chanical Integrity location, clean and	Pit. 2/24/11 27/8" work string nue in hole clean I bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held. d dispose of pit fl Rig Release Da complete to the be	cid/ Xylene, dropportion string. uids. 3/2/11 ate: Est of my knowledg Engineer Assistan	and belief.	3/4/11	
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w/ 5.) RIH w/ 2 6.) Acidized 7.) POOH lay 8.) Performed 9.) RDMO P Spud Date:	g any proposed wo bletion. Illing Unit and Ab 3/4" Bit & 6- 3 1/2" at cement and CIB (2 7/8" work strin 3/8" x 5 1/2" Arroy OH 2983'-3230've ying down work string down work string Unit, clean 2/24/20 It the information	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer of 12,000 gallons tring; RIH w/ On/o chanical Integrity location, clean and	Pit. 2/24/11 27/8" work string nue in hole clean I bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held. d dispose of pit fl Rig Release Da complete to the be	cid/ Xylene, dropportion string. uids. 3/2/11 ate: Est of my knowledg Engineer Assistan	and belief.	t.	
or recomposition of recomposition of recomposition of the second of the	g any proposed wo bletion. Illing Unit and Ab 3/4" Bit & 6- 3 1/2" at cement and CIB (2 7/8" work strin 3/8" x 5 1/2" Arroy OH 2983'-3230've ying down work string down work string Unit, clean 2/24/20 It the information	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer of 12,000 gallons tring; RIH w/ On/o chanical Integrity location, clean and	Pit. 2/24/11 27/8" work string nue in hole clean I bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held. d dispose of pit fl Rig Release Da complete to the beautiful.	cid/ Xylene, dropportion string. uids. 3/2/11 ate: Engineer Assistan melanie.reyes@ress	acaexploitation.com	3/4/11 PHONE: (432)580-850	0_
or recomp 1.) MIRU Pu 2.) RIH w/ 4 3.) Drilled ou 4.) POOH w. 5.) RIH w/ 2 6.) Acidized 7.) POOH lag 8.) Performer 9.) RDMO P Spud Date: I hereby certify that SIGNATURE Type or print name	g any proposed wo bletion. Illing Unit and Ab 3/4" Bit & 6- 3 1/2" at cement and CIB 1/2 7/8" work strin 3/8" x 5 1/2" Arroy OH 2983'-3230've ying down work string down work string Unit, clean 2/24/20 It the information	ove Ground Steel Drill Collars on 2 P @ 2820'; Conti g, drill collars and w Set 1-X Packer of 12,000 gallons tring; RIH w/ On/o chanical Integrity location, clean and	Pit. 2/24/11 27/8" work string nue in hole clean I bit. & set @ 2925'. 15% HCl 90/10 A Off Tool and inje Test, held. d dispose of pit fl Rig Release Da complete to the beautiful.	cid/ Xylene, dropportion string. uids. 3/2/11 ate: Est of my knowledg Engineer Assistan	acaexploitation.com	3/4/11	0_

