State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 5-27-2004

FILE IN TRIPLICATE **OIL CONSERVATION DIVISION** WELL API NO. 1625 N. French Dr. , Hobbs, NM SRECEIVED DISTRICT I 1220 South St. Francis Dr. 30-025-07612 Santa Fe, NM 87505 5. Indicate Type of Lease DISTRICT II 1301 W. Grand Ave, Artesia, NM 882 MAR 30 2011 STATE FFF х 1000 Rio Brazos Rd, Aztec, NM 874400BBSOCD 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A South Hobbs (G/SA) Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) 8. Well No. 1. Type of Well: 53 Oil Well Gas Well Other Temporarily Abandoned 9. OGRID No. 157984 2 Name of Operator Occidental Permian Ltd. 10. Pool name or Wildcat Hobbs (G/SA) 🖌 3. Address of Operator HCR 1 Box 90 Denver City, TX 79323 4. Well Location Line Unit Letter M Feet From The South 660 Feet From The West 660 NMPM County Range 38-E Lea Section 4 Township 19-S 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3603' GL or Closure Pit or Below-grade Tank Application Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water Pit Type \_\_\_\_\_ Depth of Ground Water \_\_\_ Below-Grade Tank: Volume bbls; Construction Material Pit Liner Thickness mil Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 12. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK **PLUG & ABANDONMENT** COMMENCE DRILLING OPNS. CHANGE PLANS **TEMPORARILY ABANDON** CASING TEST AND CEMENT JOB PULL OR ALTER CASING Multiple Completion OTHER: Х OTHER: Repair high casing pressure 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Kill well. 2. POOH w/tubing and injection equipment. 3. Clean out to 4140'. 4. Circulate clean. 5. Run back in hole w/dual injection packers. 6. Test casing and chart for the NMOCD. 7. Return well to injection. Condition of Approval: Notify OCD Hobbs office 24 hours prior of running MIT Test & Chart Per Underground Injection Control Program Manual 11.6 C Packer shall be set within or less than 100 feet of the uppermost injection perfs or open hole. y knowledge and belief. I further certify that any pit or below-grade tank has been/will be or an (attached) alternative OCD-approved , a general permit LOSGE RECORDING TO THIS OF BUILDING plan SIGNATURE adv TITLE Administrative Associate DATE 03/29/2011 TELEPHONE NO. TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com 806-592-6280 For State Use Only TITLE STATE MGE DATE-3-31-2011 APPROVED BY CONDITIONS OF APPROVAL IF ANY