## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION	
DISTRICT II  DISTRICT II  DISTRICT II  1625 N. French Dr., Hobbs, NM 88240  DISTRICT II  1020 South St. Francis Dr.  Santa Fe, NM 87505	WELL API NO. 30-025-28411
DISTRICT III  1301 W. Grand Ave, Artesia, NM 882MAR 30 2011  DISTRICT III	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 8821041	STATE X FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 DBSSOCD SUNDRY NOTICES AND REPORTS ON WELLS	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 33  8. Well No. 142
1. Type of Well: Oil Well Gas Well Other Injector	7
2. Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323  4. Well Location	
	et From The West Line
Section 33 Township 18-S Range 38-J	E NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3635' GL	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or NOTICE OF INTENTION TO:	Other Data SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEI	NS. PLUG & ABANDONMENT
	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMER  OTHER: Coiled Tubing Job X OTHER:	NS. PLUG & ABANDONMENT NT JOB
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMER  OTHER: Coiled Tubing Job X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMER  OTHER: Coiled Tubing Job X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMER  OTHER: Coiled Tubing Job X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. RU coiled tubing unit. 2. Clean out to 4300°.	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMER  OTHER: Coiled Tubing Job X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. RU coiled tubing unit. 2. Clean out to 4300'. 3. Water wash perfs 4050-4270'.	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMER  OTHER: Coiled Tubing Job X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. RU coiled tubing unit. 2. Clean out to 4300°. 3. Water wash perfs 4050-4270°. 4. Close backside & wash perfs 4050-4270° w/2500 gal of 15% NEFE HCL acid.	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion OTHER:  Coiled Tubing Job THER:  OTHER:  Coiled Tubing Job THER:  Coiled Tubing Job THER:  Coiled Tubing Job THER:  Coiled Tubing Job THER:  The coiled Tubing Job The Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  RU coiled tubing unit. Clean out to 4300°. Water wash perfs 4050-4270°. Close backside & wash perfs 4050-4270° w/2500 gal of 15% NEFE HCL acid. Circulate clean. POOH w/coiled tubing unit.	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMER  OTHER: Coiled Tubing Job X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. RU coiled tubing unit. 2. Clean out to 4300'. 3. Water wash perfs 4050-4270'. 4. Close backside & wash perfs 4050-4270' w/2500 gal of 15% NEFE HCL acid. 5. Circulate clean.	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion OTHER:  Coiled Tubing Job THER:  OTHER:  Coiled Tubing Job THER:  Coiled Tubing Job THER:  Coiled Tubing Job THER:  Coiled Tubing Job THER:  The coiled Tubing Job The Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  RU coiled tubing unit. Clean out to 4300°. Water wash perfs 4050-4270°. Close backside & wash perfs 4050-4270° w/2500 gal of 15% NEFE HCL acid. Circulate clean. POOH w/coiled tubing unit.	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion OTHER:  Coiled Tubing Job THER:  OTHER:  Coiled Tubing Job THER:  Coiled Tubing Job THER:  Coiled Tubing Job THER:  Coiled Tubing Job THER:  The coiled Tubing Job The Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  RU coiled tubing unit. Clean out to 4300°. Water wash perfs 4050-4270°. Close backside & wash perfs 4050-4270° w/2500 gal of 15% NEFE HCL acid. Circulate clean. POOH w/coiled tubing unit.	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion OTHER: Coiled Tubing Job OTHER: Coiled Tubing Job OTHER: OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. RU coiled tubing unit. 2. Clean out to 4300°. 3. Water wash perfs 4050-4270°. 4. Close backside & wash perfs 4050-4270° w/2500 gal of 15% NEFE HCL acid. 5. Circulate clean. 6. POOH w/coiled tubing unit. 7. Return well to injection.	NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any completion or recompletion.
PULL OR ALTER CASING Multiple Completion OTHER: Coiled Tubing Job X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. RU coiled tubing unit. 2. Clean out to 4300'. 3. Water wash perfs 4050-4270'. 4. Close backside & wash perfs 4050-4270' w/2500 gal of 15% NEFE HCL acid. 5. Circulate clean. 6. POOH w/coiled tubing unit. 7. Return well to injection.	NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be
PULL OR ALTER CASING	NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be the OCD-approved
PULL OR ALTER CASING	NS. PLUG & ABANDONMENT  S, including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be e OCD-approved  Associate  DATE 03/29/2011
PULL OR ALTER CASING  Multiple Completion  OTHER: Coiled Tubing Job  X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. RU coiled tubing unit. 2. Clean out to 4300'. 3. Water wash perfs 4050-4270'. 4. Close backside & wash perfs 4050-4270' w/2500 gal of 15% NEFE HCL acid. 5. Circulate clean. 6. POOH w/coiled tubing unit. 7. Return well to injection.  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE	NS. PLUG & ABANDONMENT  S, including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be e OCD-approved  Associate  DATE 03/29/2011
PULL OR ALTER CASING	NS. PLUG & ABANDONMENT  INT JOB  Is, including estimated date of starting any completion or recompletion.  That any pit or below-grade tank has been/will be the OCD-approved  Associate  DATE 03/29/2011  TELEPHONE NO. 806-592-6280
PULL OR ALTER CASING  Multiple Completion  OTHER: Coiled Tubing Job  X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. RU coiled tubing unit. 2. Clean out to 4300'. 3. Water wash perfs 4050-4270'. 4. Close backside & wash perfs 4050-4270' w/2500 gal of 15% NEFE HCL acid. 5. Circulate clean. 6. POOH w/coiled tubing unit. 7. Return well to injection.  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE	NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be the OCD-approved  Associate  DATE 03/29/2011  TELEPHONE NO. 806-592-6280