Submit 3 Copies To Appropriate District  State of New Mexico	Form C-103			
Office State of New Weekley  District   Energy, Minerals and Natural Resources	Revised March 25, 1999			
1625 N. French Dr., Hobbs, NM 87240	WELL API NO.			
District II 811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION	30-025-34621			
District III 2040 South Pochage	5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410  District IV  Santa Fe, NM 87505	STATE X FEE			
2040 South Pacheco, Santa Fe, NM 87505	6. State Oil & Gas Lease No.			
SUNDRY NOTICES AND REPORTS ON WELLS	A-1375-45  7. Lease Name or Unit Agreement Name:			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Lisa State			
1. Type of Well: Oil Well  Gas Well  Other	Disa State			
2. Name of Operator  Xeric Oil & Gas Corporation	8. Well No.			
3. Address of Operator P. O. Box 352, Midland, TX 79701	9. Pool name or Wildcat  Eumont Y-SR-0			
4. Well Location	Editore 1-5k-Q			
Unit Letter B: 660 feet from the North line and 1980 feet from the East line				
Section 19 Township 20S Range 36E	NMPM Lea County			
10. Elevation (Show whether DR, RKB, RT, GR, e				
11. Check Appropriate Box to Indicate Nature of Notice	Report or Other Data			
	SSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WO				
TEMPORARILY ABANDON	RILLING OPNS. PLUG AND			
PULL OR ALTER CASING  MULTIPLE  CASING TEST A COMPLETION  CEMENT JOB	ABANDONMENT AND			
in the state of the				
OTHER: OTHER:				
12. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta	give pertinent dates, including estimated date ch wellbore diagram of proposed completion			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date ch wellbore diagram of proposed completion			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta	ch wellbore diagram of proposed completion			
Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.      MIRU Pulling Unit.	ch wellbore diagram of proposed completion			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag.	ch wellbore diagram of proposed completion			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud.	ch wellbore diagram of proposed completion			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag.	ch wellbore diagram of proposed completion			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'.	ch wellbore diagram of proposed completion			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag.	ch wellbore diagram of proposed completion			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'.	ch wellbore diagram of proposed completion			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'.	ch wellbore diagram of proposed completion			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'.	ch wellbore diagram of proposed completion			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'.	ch wellbore diagram of proposed completion			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'. 7) Install dry hole marker & clean location.	ch wellbore diagram of proposed completion  A 2004  A			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'. 7) Install dry hole marker & clean location.	ch wellbore diagram of proposed completion  ARR 2004  POR Hobbs  OCD  CONTROL OF THE PROPOSED AND THE PROPOS			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'. 7) Install dry hole marker & clean location.	dge and belief.  Analyst DATE 2/27/04			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'. 7) Install dry hole marker & clean location.  I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Mague May That I Production	dge and belief.  Analyst  DATE 2/27/04  43-683-3171			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'. 7) Install dry hole marker & clean location.  I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE May May TITLE Production.  Type or print name Angie Crawford	dge and belief.  Analyst  DATE 2/27/04  43-683-3171			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'. 7) Install dry hole marker & clean location.  I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE May May That Production  Type or print name Angie Crawford  (This space for State use)	dge and belief.  Analyst  DATE 2/27/04  43-683-3171			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'. 7) Install dry hole marker & clean location.  I hereby certify that the information above is true and complete to the best of my knowled starting and the starting	dge and belief.  Analyst  DATE 2/27/04  43-683-3171			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'. 7) Install dry hole marker & clean location.  I hereby certify that the information above is true and complete to the best of my knowledge of the state use.  Type or print name Angie Crawford  (This space for State use) OC FIELD REPRESE COMMISSION MUST BE NOTIFIED 24	dge and belief.  Analyst  DATE 2/27/04  43-683-3171			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'. 7) Install dry hole marker & clean location.  I hereby certify that the information above is true and complete to the best of my knowledge of the state use.  Type or print name Angle Crawford  (This space for State use)  APPPROVED BY  Conditions of approval, if any:  THE COMMISSION MUST BE NOTIFIED 24  HOURS PRIOR TO THE SECININING OF	dge and belief.  Analyst  DATE 2/27/04  43-683-3171			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.  1) MIRU Pulling Unit. 2) Spot 25 sx @3830' & tag. 3) Circulate hole w/9.5# mud. 4) Spot 25 sx @ 2000' & tag. 5) Spot 25 sx @ 380'. 6) Spot 5 sx @ 50'. 7) Install dry hole marker & clean location.  I hereby certify that the information above is true and complete to the best of my knowledge of the state use.  Type or print name Angie Crawford  (This space for State use) OC FIELD REPRESE COMMISSION MUST BE NOTIFIED 24	dge and belief.  Analyst  DATE 2/27/04  43-683-3171			

XERIC OIL & GAS CORP. WELLBORE DIAGRAM

WELL: LISA State	e #2		
COUNTY: Lea	30-025-3462/		·
STATE: NIN	· · · · · · · · · · · · · · · · · · ·		
		KER	
			.*
HOLE SIZE: 12'4"			
CASING: 86 @ 381 NO CEMENTED WITH: 2505X			
CEMENT TOP: Surt.	•		
	TOUT TO THE TOTAL CONTROL OF THE		
			31-1234567
TUBING: 115 ts @ 3733			NAR 2004
Rods:		52627283	REULIVED !
PUMP:		PERF	Hobbs OCD
PACKER:		3836	3906
		CIBP@ 3950'	1
		3965	
77/8		4000	- 70'
HOLE SIZE:		2000	4860°
CASING: 5/2" @4900		P8TD: _ TD: <u>C</u>	
CEMENTED WITH: 12255X	en de la companya de		+-(00