Submit 3 Copies To Appropriate District Office	State of Ne		Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and	d Natural Resources	Revised June 10, 2003 WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-28839 5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE X FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, N	NM 87505	6. State Oil & Gas Lease No.
87505	CES AND DEPOPTS ON W	/EII S	K5954 7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Mesa State
1. Type of Well: Oil Well X Gas Well Other			8. Well Number 2
2. Name of Operator			9. OGRID Number
CONCHO RESOURCES INC. 3. Address of Operator 550 W. TEXAS, SUITE 1300			193407 10. Pool name or Wildcat
MIDLAND, TX 79701			North Shoebar-Wolfcamp
4. Well Location			
Unit Letter M :	feet from the So	outh line and	510 feet from the West line
Section 14	Township 16S	Range 35E	NMPM County Lea
	11. Elevation (Show wheth 3979 GR	ner DR, RKB, RT, GR, et	tc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN			BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WOR	RK
TEMPORARILY ABANDON	CHANGE PLANS		ILLING OPNS. PLUG AND MMISSION MUST BEBANDONIMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING (TEST A)	MRIOR TO HE SCHNING OF AG OPERATIONS FOR THE C-103
OTHER:			APPROVED.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
Contact NMOCD 24 hrs. prior to commencement of abandonment. 1. MIRU. Kill tbg. w/FW & NU 3M# manual dbl BOP. Release pkr @ 10237 &POH LD 326 jts 2 3/8" 4.7# N80 EUE 8rd tbg &			
BHA.			
2. RIH & set CiBP @ 10150'. Cap CIBP w/35' cmt. 3. PU w/s & RIH to 10100'. Circ & load hole w/9# mud. POH.			
4. RU csg. jacks & free point 5 1/2" string. Make initial cut at 9000' & attempt to retrieve csg. If unable to pull from this point			
obtain permission from NMOCD to attempt cut and pull at highter depth. POH & LD csg. 5. RIH w/w/s & spot 35 sx cmt plug f/8920' - 9050' (50' inside csg. stub). PU & WOC 2 hrs. RIH & tag.			
6. PU & spot 35 sx cmt. plug f/6425'6525'.			
7. PU & spot 45 sx cmt. plug f/4360'-4460'. PU & WOC 2 hrs. RIH & tag. 8. PU & spot 35 sx cmt. plug f/2000 - 2100'.			
9. PU & spot 35 sx cmt. plug f/352'-452'. PU & WOC 2 hrs. RIH & tag.			
10. PU to 30' & spot 10 sx surface plug. POH. 11. Cut off wellhead. Weld on plate & DH marker. Back fill cellar.			
12. RDMO Csg. Pullers			
13. MO all equipment and clean le			11.11.6
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE REGULATORY ANALYST DATE 03/19/2004 BCOFFMAN@CONCHORESOURCES.COM			
Type or print name BRENDA COFF	MAN E-	mail address:	Telephone No. (432)685-4373
(This space for State use) OC FIELD REPRESENTATIVE II/STAFF MANAGER			
APPPROVED BY Conditions of approval, if any:	W.Wink TIT		DATE 1/2 3 2034