NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		•••••
	John Marian Congression	5a. Indicate Type of Lease
U.S.G.S.		
LAND OFFICE		State Fee. X
OPERATOR		5. State Oil & Gas Lease No.
CLINDO	V.NOTICES AND DEDODES ON WITH A	mmmmmmk
SUNDK	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ON FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
USE **APPLICATIO	ON FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1.		7. Unit Agreement Name
OIL X WELL	OTHER.	
2. Name of Operator	VIII.	8. Farm or Lease Name
Sunray DX 011 Company	<u>y</u>	W. Crenshaw
3. Address of Operator		9. Well No.
P. O. Box 1416 - Rosw	well New Merico	1
4. Location of Well	WCII; New Healto	10. Field and Pool, or Wildcat
		1
UNIT LETTER A	660 FEET FROM THE North LINE AND 660 FE	ET FROM Wildcat
Rect	1/4 1_N 21 1	
THE LAST. LINE, SECTION	N 14 TOWNSHIP 1-N RANGE 31-E	_ NMPM.
mmmmmmmmm		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4350 DF (Est.)	Curry
16.		•
Check A	Appropriate Box To Indicate Nature of Notice, Report	or Other Data
NOTICE OF IN	TENTION TO: SUBSE	QUENT REPORT OF:
		<u></u> -1
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	X
	OTHER	
	OTRER	
OTHER		
17 Describe Etenand or Completed One	exettene (Clearly state all novines details and in a six and in a	
17. Describe Proposed or Completed Ope work) SEE RULE 1703.	erations (Clearly state all pertinent details, and give pertinent dates, in	ncluding estimated date of starting any proposed
17. Describe Proposed or Completed Ope	erations (Clearly state all pertinent details, and give pertinent dates, in	ncluding estimated date of starting any proposed
work) SEE RULE 1103.		ncluding estimated date of starting any proposed
17. Describe Proposed or Completed Ope work) SEE RULE 1703. 1. Moved in and rigg		ncluding estimated date of starting any proposed
work) SEE RULE 103. 1. Moved in and rigg	ged up.	ncluding estimated date of starting any proposed
work) SEE RULE 103. 1. Moved in and rigg		ncluding estimated date of starting any proposed
1. Moved in and rigg 2. Spudded 11" hole	ged up. and drilled to 3081.	
1. Moved in and rigg 2. Spudded 11" hole	ged up. and drilled to 3081.	
 Moved in and rigg Spudded 11" hole Ran 9 jts, 8-5/8" 	ged up. and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Cla	
1. Moved in and rigg 2. Spudded 11" hole	ged up. and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Cla	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs	ged up. and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Cla	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test 5. Now drilling 7-7/	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Class to surface. t BOP & csg to 1000# for 30 min. OK. /8" hole @ 2865' (1-1-68).	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test 5. Now drilling 7-7/	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK.	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test 5. Now drilling 7-7/	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Class to surface. t BOP & csg to 1000# for 30 min. OK. /8" hole @ 2865' (1-1-68).	
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test 5. Now drilling 7-7/	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK. /8" hole @ 2865' (1-1-68).	ss "C" w/2% CaCl ₂ .
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test 5. Now drilling 7-7/	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Class to surface. t BOP & csg to 1000# for 30 min. OK. /8" hole @ 2865' (1-1-68).	ss "C" w/2% CaCl ₂ .
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test 5. Now drilling 7-7/	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK. /8" hole @ 2865' (1-1-68).	ss "C" w/2% CaCl ₂ .
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test 5. Now drilling 7-7/	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK. /8" hole @ 2865' (1-1-68).	neer DATE January 3, 1968
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test 5. Now drilling 7-7/	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Clasto surface. t BOP & csg to 1000# for 30 min. OK. /8" hole @ 2865' (1-1-68).	neer DATE January 3, 1968
1. Moved in and rigg 2. Spudded 11" hole 3. Ran 9 jts, 8-5/8" Circulated 30 sxs 4. WOC 18 hrs. Test 5. Now drilling 7-7/	and drilled to 308'. ', 24#, J-55 to CP 305'. Cmt w/200 sxs Class to surface. t BOP & csg to 1000# for 30 min. OK. /8" hole @ 2865' (1-1-68).	neer DATE January 3, 1968