

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 7088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State <input type="checkbox"/> For <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name G. L. Jensen Etal
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat Cisco
12. County Curry

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
Name of Operator GULF OIL CORPORATION
Address of Operator P. O. Box 670, Hobbs, NM 88240
Location of Well UNIT LETTER <u>B</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>18</u> TOWNSHIP <u>4N</u> RANGE <u>32E</u> NEUTRAL

15. Elevation (Show whether DF, RT, GR, etc.)

4580' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CALL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimate date of starting any proposed work) SEE RULE 1103.

Go in hole open-ended; lay down drill pipe. Plug well with 50 sacks Class "C" neat at 6910'-6800', 50 sacks Class "C" neat at 6435'-6335', 50 sacks Class "C" neat at 5100'-5000', 50 sacks Class "C" neat at 3275'-3175', 50 sacks Class "C" neat at 1685'-1585', 10 sacks Class "C" neat plug at surface. Nipple down BOP, cut off head and install dry hole marker. Complete after drilling - dry. Completed 5-14-80.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY Glyn Stone TITLE Area Engineer DATE 6-2-80
APPROVED BY Eddie Seay TITLE OIL & GAS INSPECTOR DATE
CONDITIONS OF APPROVAL, IF ANY: