

DUPLICATE

RAILROAD COMMISSION OF TEXAS
AUSTIN, TEXAS

RECEIVED

NOV 14 1951

OIL CONSERVATION COMMISSION
HOBBBS-OFFICE

Statement of the Condition of the Well AFTER Shooting or Acidizing

Required by Rules and Regulations of the Railroad Commission

Name of owner or operator The Texas Company Date November 13, 19 51Address Box 1270, Midland, Texas
(Give street address or P. O. box number)Well Number 82Description of Lease: Name P. L. Fuller County ScurryBlock No. 97 Lge. No. --- Sec. No. 650 Labor No. --- Lot No. ---Have you filed a log of this well? Yes Inner string of casing set at 6870 ft. Water 9 %

SHOT

Depth to top of the Pay _____ ft.

Thickness of the pay shot _____ ft.

Size of shot used _____ quarts

Production before shot _____ bbls.

Production after shot _____ bbls.

Production increased _____ bbls.

Production decreased _____ bbls.

Name of torpedo
company or shooter _____

Remarks: _____


ACIDIZED

Depth to top of the Pay 6867 ft.Thickness of the pay acidized 12 ft.Am't. of acid used 5000 gallonsProduction before acid 31 bbls.Production after acid 77 in 17 hrs. bbls.Production increased 29 bbls.

Production decreased _____ bbls.

Name of acid company
or treater Dowell Chemical Co.

Remarks: _____



Representative of the Company

File this report in duplicate with the Deputy Supervisor of District in which well is located.