## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

ORIGINAL SIGNED BY JERRY SENTON

APPROVED BY DISTRICT I SUPERIVISOR

CONDITIONS OF APPROVAL, IF ANY:

## OIL CONSERVATION DIVISION

SEP 17 1984

	DISTRIBUTION	P. O. BOX 2088			
	SANTA FE	SANTA FE, NEW MEXICO 87501	<b>Revised 10-1-7</b>		
	FILE		Sa. Indicate Type of Lease		
	U.S.G.S.	7			
	LAND OFFICE		State X Fee		
	OPERATOR		5, State Oil & Gas Lease No.		
	<u> </u>	<b>-</b>	B-9946		
			THE THE THE THE THE THE		
	SUNDF	RY NOTICES AND REPORTS ON WELLS  OPOSALS TO DRILL OR TO OCCEPTO OR PLUG BACK TO A DIFFERENT RESERVOIR.  TION FOR PERMIT —" (FORM C-101) FOR SUCK PROPOSALS.)			
	THE NOT USE THIS FOR FOR PAINT SEU TON DOLL	TION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
Π.			7. Unit Agreement Name		
OIL GAS OTHER- Water Injection			Northeast Caprock Queen Unit		
		orner. Water injection	8. Farm or Lease Name		
2. Name of Operator			Northeast Caprock		
	MR Oil Compa	nv	Oueen Unit		
3. Ac	idress of Operator		9. Well No.		
			10		
		ahans, Texas 79756	10. Field and Pool, or Wildcat		
	ocation of Well	•	ly, Field and Pool, or windcar		
i	P	660 FEET FROM THE SOUTH LINE AND 660 FEET FROM	Caprock Queen		
İ	UNIT LETTER	TEL FROM THE CIRC AND /CET / NOW			
	F	16 120 220			
	THELAST_ LINE, SECTI	ION 16 TOWNSHIP 12S RANGE 32E NMPM.			
111		15. Elevation (Show whether DF, RT, GR, etc.)	12. County		
		4367 GL	Lea		
16.					
10.	Check	Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data		
	NOTICE OF 1	NTENTION TO: SUBSEQUENT	REPORT OF:		
PER	FORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING		
TEM	PORARILY ABANDON X	COMMENCE DRILLING OPHS.	PLUG AND ABANDOHMENT		
PUL	L OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB			
		OTHER"			
•	THER				
		perations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any propaga		
	Describe Proposed or Completed O Uprk) SEE RULE 1103.	perations (Clearly state att pertinent details, and give pertinent dates, including	carring any proposed		
-	,				
		4			
	1. 3	Set 5½" Cast Iron Bridge Plug @ 2970'+			
	2 1				
	2.	Dump or spot 35' cement on top of B.P.			
	_	Load hole with 9.5# brine mud.			
	3. 1				
4. Test casing to 500 psi.					
		too cabing to you por.			
	5. 5	Temporarily abandon for lease evaluation.			
		•			
	•				
	THE OAK	th trevens a			
	Inc CCA	MISSION MUST BE NOTIFIED			
	24 HOUR	S PRIOR TO COMMENCING WORK			
		TO SOMMENOING WORK			
10.1	hereby certify that the information	shove is true and complete to the best of my knowledge and belief.			

RECEIVED

SEP 1 4 1984

OCC. Hobbe dance