

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION  
HOBBS OFFICE O.C.C.

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

JAN 6 11 46 AM '67

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TRAINER CORPORATION	8. Farm or Lease Name Johnson
3. Address of Operator P. O. Box 1100, Hobbs, New Mexico	9. Well No. #1
4. Location of Well UNIT LETTER N 1980 FEET FROM THE West LINE AND 660 FEET FROM THE South LINE, SECTION 12 TOWNSHIP 9S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4327 GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to:

1. Spot 20 sx. plug in 4 1/2" casing 8550-8860.
2. Cut 4 1/2" casing at 7950 and pull.
3. Spot 25 sx. plug in and out of 4 1/2" casing stub at 7950.
4. Spot 25 sx. plug at 6800.
5. Spot 25 sx. plug at 5300.
6. Spot 25 sx. plug at 5860 in and out of 9 5/8" casing shoe.
7. Spot 10 sx. plug at surface and erect regulation 4" marker.
8. Clean and level location.

*Revised to P/A 1/11/67*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. W. Trainer TITLE President DATE 1-5-67

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: