

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name E-1811
2. Name of Operator Amerada Hess Corporation		8. Farm or Lease Name State BT"D"
3. Address of Operator 1209 South Main, Lovington, New Mexico		9. Well No. 5
4. Location of Well UNIT LETTER <u>0</u> <u>660'</u> FEET FROM THE <u>South</u> LINE AND <u>1980'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>35</u> TOWNSHIP <u>11-S</u> RANGE <u>33-E</u> NMPM.		10. Field and Pool, or Wildcat Bagley-Pennsylvanian
15. Elevation (Show whether DF, RT, GR, etc.) 4245' D.F.		12. County Lea

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

### 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

State BT"D" #5 - Spot 35 sack plug through 2-3/8" tubing in 5-1/2" Csg. 7980' to 7700'. Cut 5-1/2" Csg. @ 3791', spot 70 sack plug through 2-3/8" tubing 3875' to 3775'. Cut 8-5/8" Csg. @ 289' and spot 100 sack plug through 2-3/8" tubing 335' to 235'. Spot 20 sack plug 0' to 24' and install Dry Hole Marker and clean location. Work completed on 2-20-73. Csg. was loaded with Salt-Water Mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. W. [Signature] TITLE Area Supt. DATE 3-19-73  
 APPROVED BY John W. [Signature] TITLE Commissioner DATE 3-19-73  
 COUNTY OF APPROVAL, IF ANY: \_\_\_\_\_