NO. OF COPIES RECEIVED	¬ .				
DISTRIBUTION				Form C-103	
	7		•	Supersedes Of C-102 and C-1	
SANTA FE	NEW MEXICO O	IL CONSERVATION COMMI	SSION	Effective 1-1-	
FILE					- ,
U.S.G.S.				State X	Fee .
LAND OFFICE				5. State Oil & Ga	
OPERATOR				E1811	*******
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)					
OIL X GAS WELL				7. Unit Agreemen	t Name
2. Name of Operator				8. Farm or Lease Name State BT"D"	
Amerada Hess Corporation					
3. Address of Operator 1209 South Main - Lovington, New Mexico				9. Well No. #1	
4. Location of Well				10. Field and Pool, or Wildcal	
UNIT LETTER N 6601 PEET FROM THE South LINE AND 19801			O1 PEET PROM	Bagley Strawn	
•	TION 2 TOWNSHIP	•			
THE					7//////////////////////////////////////
		w whether DF, RT, GR, etc.)		12. County Lea	
	4250)! G.R.		Tee	<i>-411111111</i>
PULL OR ALTER CASING	CHANGE FLANS	OTHER			
OTHER					
•					
work) SEE RULE 1103.	•				
State BT"D" #1 - Set Los cer 8-9	Cast Iron Bridge P. ad Hole w/Salt Watement plug 4050' to 5/8" Csg. @ 1000' & ug 240' to 340'. Ster plugging operatan to start pluggin	lug @ 9250' w/35 sad r Mud and cut 5-1/2 3950', and spot 35 of spot 100 sack plug pot 20' plug top 13 ion will clean loca g operations on 4/1	cks of Cemen " Csg. @ 400 sack plug 39 1050" to 95 -3/8" w/4"x1 tion for Sta	t on top of 00' & spot 3 30' to 3830 0' & spot 1 0' Dry Hole	plug. 35 sack 01. Cut 00 sack Marker.
State BT"D" #1 - Set Los cer 8- pli Aft	Cast Iron Bridge P. ad Hole w/Salt Watement plug 4050' to 5/8" Csg. @ 1000' & ug 240' to 340'. Ster plugging operatan to start pluggin	lug @ 9250' w/35 sac r Mud and cut 5-1/2 3950', and spot 35 spot 100 sack plug pot 20' plug top 13 ion will clean loca g operations on 4/1	cks of Cemen "Csg. 9 400 sack plug 39 1050' to 95 -3/8" w/4"x1 tion for Sta 6/73	t on top of 00' & spot 3 30' to 3830 0' & spot 1 0' Dry Hole	plug. 5 sack 0'. Cut 00 sack Marker.
State BT"D" #1Set Los cer 8-: pli	Cast Iron Bridge P. ad Hole w/Salt Watement plug 4050' to 5/8" Csg. @ 1000' & ug 240' to 340'. Ster plugging operatan to start pluggin	lug @ 9250' w/35 sac r Mud and cut 5-1/2 3950', and spot 35 spot 100 sack plug pot 20' plug top 13 ion will clean loca g operations on 4/1	cks of Cemen "Csg. 9 400 sack plug 39 1050' to 95 -3/8" w/4"x1 tion for Sta 6/73	t on top of 00' & spot 3 30' to 3830 0' & spot 1 0' Dry Hole	plug. 5 sack 0'. Cut 00 sack Marker.

CHAN TO COLD OF APPROVAL, IF ANY!