

IIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: Santa Fe Pacific Unit Well No. 5
Field: Crossroads (Devonian)
County: Lea State: New Mexico

RECOMMENDED PROCEDURE:

- 20 ball sealers will be required.
6. Clean out, swab, and test the well as required.
7. Retrieve the bridge plug.
8. Run the tubing and Roda pump back in the hole.
9. Return the well to production.