STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	 •
00, 0/ {0+1EB \$1CE1948	•
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

LITTIONS OF ACPROVAL, IF ANY:

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 Revised 10-1-78

FILE		SANTA FE, NE	W MEXICO 87501	
U.S.G.S.			•	Sa. Indicate Type of Lease
LAND OFFICE				State X Fee
OPERATOR			• .	5. State Oil 6 Gas Lease No.
	·			NM 058102
	SUNDRY NOTIC	CES AND REPORTS OF	JWELLS	mmmillinin.
IDD NOT USE THIS FO	BM FOR PROPOSALS TO	DRILL OR TO DEEPEN OF PLUG RMIT -" (FORM C-101) FOR St	BACK TO A BIRECOCHE GROOMS	
1.			CH PHOPOSALS.)	7. Unit Agreement Name
	OTHER-		per order #WEX-539	· ·
2. Name of Operator	Flying "M" (SA)			
z. Maine di Operaio.	B. Farm or Lease Ivame			
<u>Coastal Oil & Ga</u>	Tract 10			
3. Address of Operator	9. Well No.			
P. O. Box 235	Midland, Texa	as 79702		2
4. Location of Well	10. Field and Pool, or Wildcat			
UNIT LETTER L	Flying "M" (SA)			
<u> </u>			, , , , , , , , , , , , , , , , , , , ,	
South .		16 9-4	S RANGE 33-E	
THE DOGETT	. IN C. SECTION	TOWNSHIP	Z NANGE JJJ-II	
		15. Elevation (Show whethe	r DF, RT, GR. etc.)	12. County
		,		Lea
^{16.}	<i>immi</i>			
•••	Check Appropri	ate Box To Indicate:	Nature of Notice, Report o	r Other Data
NOTIC	CE OF INTENTIO	N TO:	SUBSEQU	JENT REPORT OF:
	_			
PERFORM REMEDIAL WORK]	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ASAHDON]		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING]	EMANGE PLANS	CASING TEST AND CEMENT JOB	آ
-	-		OTHER	
OTHER Convert to) water inject	tion x		
17. Describe Proposed or Co	mpieted Operations (Slearly state all pertinent de	tails, and give pertinent dates, incl	luding estimated date of starting any proposed
work) SEE RULE 1103.			4	
Tract 10 #2 to be	a converted no	er Order No. WFX-5	30	
11act 10 #2 to be	: converted pe	or order No. Wrx-	139.	
1 MTDH ****11 **		DII annula desta des	126 1	1 man 21
1. MIRU WELL S	servicing unit	. Pu workstring,	, bit and casing scrap	er and TIH. Clean out
	Circ hole clea			
		casing gun. Perf	orate interval from 4	500'-4508' with 2 SPF.
POOH with gu				
			35' and treat perfs 44 .	54'-4508' with 6000
		ack load. POOH.		
4. Pick up inje	ection packer	and Salta-lined t	ubing and TIH. Set	packer at ±4360'. Flange
up wellhead	and place wel	ll on injection.		
_				
				`
			• • •	
			· ·	
•				
	•			
I hereby certify that the i	nformation above is to	rue and complete to the best	of my knowledge and belief.	
- •	4		•	
יובלם ז מ	RI C-1	_		
B. L. Smith	11/2 much		etroleum Engineer	• February 13, 1985
animital CM	NED BY JERRY SE	KTON		
ORIGINAL SIG	CT I SUPERVISOR			FEB 1 5 1985
DISTRIC	57 1 801			DATE

RESERVED

FEB 14 1985

HOBER OFFICE