SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION SANTA FE U.S.G.S. LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name OTHER- Drilling Well
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION Effective 1-1-65 U.S.G.S. LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name
LAND OFFICE OPERATOR S. State Oil & Gas Lease No. E=7324 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name
LAND OFFICE OPERATOR S. State Oil & Gas Lease No. E=7324 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name
LAND OFFICE OPERATOR S. State Oil & Gas Lease No. E=7324 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 1. 7. Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name
1. 7. Unit Agreement Name
OIL GAS THE STATE OF THE STATE
WELL WELL OTHER. Drilling Well
2. Name of Operator 8. Farm or Lease Name
The Louisiana Land and Exploration Company State 14
3. Address of Operator 9. Well No.
1605 Wilco Bldg., Midland, Texas 79701
4. Location of Well 10. Field and Pool, or Wildcat
UNIT LETTER P 660 FEET FROM THE SOUTH LINE AND 660 FEET FROM MIDDLE Lane Penn
UNIT LETTER FOM THE SOUT LINE AND SOUT FEET FROM HILDER FORTE
Fact 16 10 C 33 F
THE <u>East</u> LINE, SECTION 14 TOWNSHIP 10.5 RANGE 33.E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 12. County
VIIIIIIIIIII
4197 gr., 4210 KB Lea (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPAS. PLUG AND ABANDONMENT
PULL OR ALTER CASING LOSING TEST AND CEMENT JOB
OTHER
OTHER
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dutes, including estimated date of starting any propo
work) SEE RULE 1703.
Spud 12:30 A.M. CST 2-20-67
Ran 12 jts. new 13 3/8" 48# H-40 csg. Set @ 410 and cemented w/ 350 sx reg. neat w/ 29
CaCl. Circ. cement to surface. Plug down 4:45 P.M. 2-20-67. WOC 22 hrs. Test csg. to
1000# PSI for 30" 2-21-67. TEst OK.
1000# PSI for 30" 2-21-67. TEst OK.
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28'-32# H-40, 2366'-24# J-55, 226'-28# H-40, 1396'-#
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28*-32# H-40, 2366*-24# J-55, 226*-28# H-40, 1396*-# 32# J-55). Set @ 4007* and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28"-32# H-40, 2366"-24# J-55, 226"-28# H-40, 1396"-# 32# J-55). Set @ 4007" and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28*-32# H-40, 2366*-24# J-55, 226*-28# H-40, 1396*-# 32# J-55). Set @ 4007* and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28*-32# H-40, 2366*-24# J-55, 226*-28# H-40, 1396*-# 32# J-55). Set @ 4007* and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK.
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28"-32# H-40, 2366"-24# J-55, 226"-28# H-40, 1396"-# 32# J-55). Set @ 4007" and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28"-32# H-40, 2366"-24# J-55, 226"-28# H-40, 1396"-# 32# J-55). Set @ 4007" and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK. Ran temp. survey - top cement @ 3120.
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28*-32# H-40, 2366*-24# J-55, 226*-28# H-40, 1396*-# 32# J-55). Set @ 4007* and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK.
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28"-32# H-40, 2366"-24# J-55, 226"-28# H-40, 1396"-# 32# J-55). Set @ 4007" and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK. Ran temp. survey - top cement @ 3120.
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28"-32# H-40, 2366"-24# J-55, 226"-28# H-40, 1396"-# 32# J-55). Set @ 4007" and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK. Ran temp. survey - top cement @ 3120.
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28"-32# H-40, 2366"-24# J-55, 226"-28# H-40, 1396"-# 32# J-55). Set @ 4007" and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK. Ran temp. survey - top cement @ 3120.
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28"-32# H-40, 2366"-24# J-55, 226"-28# H-40, 1396"-# 32# J-55). Set @ 4007" and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK. Ran temp. survey - top cement @ 3120.
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28'-32# H-40, 2366'-24# J-55, 226'-28# H-40, 1396'-# 32# J-55). Set @ 4007' and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK. Ran temp. survey - top cement @ 3120. WOC 16 1/4 hrs. Test 8 5/8 to 1200# PSI. Test OK.
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28'-32# H-40, 2366'-24# J-55, 226'-28# H-40, 1396'-# 32# J-55). Set @ 4007' and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK. Ran temp. survey - top cement @ 3120. WOC 16 1/4 hrs. Test 8 5/8 to 1200# PSI. Test OK.
1000# PSI for 30" 2-21-67. TEst OK. Ran 124 jts. new 8 5/8" csg. (28'-32# H-40, 2366'-24# J-55, 226'-28# H-40, 1396'-# 32# J-55). Set @ 4007' and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK. Ran temp. survey - top cement @ 3120. WOC 16 1/4 hrs. Test 8 5/8 to 1200# PSI. Test OK.
1000# PSI for 30" 2-21-67. TEST OK. Ran 124 jts. new 8 5/8" csg. (28'-32# H-40, 2366'-24# J-55, 226'-28# H-40, 1396'-# 32# J-55). Set @ 4007' and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK. Ran temp. survey - top cement @ 3120. WOC 16 1/4 hrs. Test 8 5/8 to 1200# PSI. Test OK.
Ran 124 jts. new 8 5/8" csg. (28°-32# H-40, 2366°-24# J-55, 226°-28# H-40, 1396°-# 32# J-55). Set @ 4007° and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK. Ran temp. survey - top cement @ 3120. WOC 16 1/4 hrs. Test 8 5/8 to 1200# PSI. Test OK.
Ran 124 jts. new 8 5/8" csg. (28°-32# H-40, 2366°-24# J-55, 226°-28# H-40, 1396°-# 32# J-55). Set @ 4007° and cemented w/ 200 sx Incor Poz w/ 2% gel plus 4# salt/sack and 100 sx Incor w/ 2% CaCl and 4# salt/sack. Plug down 7:45 A.M. 2-27-67. Maximum pressure 1400#. Released, float held OK. Ran temp. survey - top cement @ 3120. WOC 16 1/4 hrs. Test 8 5/8 to 1200# PSI. Test OK.