

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P.O. Box 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>	
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>5. State Oil & Gas Lease No. OG 584</p>	
<p>2. Name of Operator Read & Stevens, Inc.</p>		<p>7. Unit Agreement Name -</p>	
<p>3. Address of Operator P.O. Box 1518, Roswell, NM 88201</p>		<p>8. Farm or Lease Name Skelly State</p>	
<p>4. Location of Well UNIT LETTER <u>H</u> <u>2130</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE. SECTION <u>10</u> TOWNSHIP <u>10S</u> RANGE <u>33E</u> NMPM</p>		<p>9. Well No. 1</p>	
<p>5. Elevation (Show whether DF, RT, GR, etc.) 4225' GL</p>		<p>10. Field and Pool, or Wildcat Und. Flying "M" San Andres</p>	
<p>12. County Lea</p>		<p>XXXXXXXXXXXXXXXXXXXX</p>	

<p>Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>	
<p>NOTICE OF INTENTION TO:</p>	<p>SUBSEQUENT REPORT OF:</p>
<p>PERFORM REMEDIAL WORK <input type="checkbox"/></p>	<p>REMEDIAL WORK <input type="checkbox"/></p>
<p>TEMPORARILY ABANDON <input type="checkbox"/></p>	<p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p>
<p>PULL OR ALTER CASING <input type="checkbox"/></p>	<p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p>
<p>OTHER <input type="checkbox"/></p>	<p>OTHER <input type="checkbox"/></p>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-25-83 Set CIPB @ 4525' w/ 25sx cmt, 250' fill, load hole w/ mud. Plug @ 2630, 25sx, Plug @ 2126, 25sx, Pull to 1941'. Circ out cmt.

8-26-83 Tag plug @ 1950'. Perf @ 1900 w/ 4 shots. Squeeze w/100sx cmt, Displace cmt to 1850'. SION

8-27-83 Spot 10sx surface plug w/ dryhole marker. Clean location. Pick up flow lines. cover pit.

Cleaning up location. Will notify when ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bruce Stobbs TITLE Drilling & Production Manager DATE 8-24-83

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE MAR 25 1988

CONDITIONS OF APPROVAL, IF ANY

RECEIVED

SEP 9 1983

O.C.D.
MOBBS OFFICE