

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>17-25-22064</u>
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Bison Petroleum Corporation

3. Address of Operator
5809 S. Western Suite 200 Amarillo Texas

4. Well Location
Unit Letter O : 660 Feet From The South Line and 2110 Feet From The East Line

Section 24 Township 11-S Range 33-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4217.6' GR

7. Lease Name or Unit Agreement Name
E P Person

8. Well No.
3

9. Pool name or Wildcat
In the Permo Penn

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in Rig UP Plugging Unit Pull rods + Pump Pull 2 7/8" Tbg.
2. Rig wireline unit Run CIBP To 9778 +- Set Plug, Dump ³⁵ ~~20~~ ' of Cement
3. Run Tbg. Load hole with 10# mud laden brine Pump 100' Plug at 6850 (25 SKs +-)
4. Pump 100' Plug at 5400 - 5300' (25 SKs +-) Pull out with Tbg.
5. Pick UP on 5 1/2" Csq. Shoot Pipe at free Point Lay down Csq.
6. Run Tbg. To Cut Point 50' in 50' out Cement Plug. (40 SKs +-) Tag with Tbg.
7. Pump 100' Plug 4050 - 3950 (45 SKs +-) Tag with Tbg. Pull out of hole
8. Perforate well 1950' Run in Tbg. SPOT 100' Plug (40 SKs +-) Pull out with Tbg.
9. Pick UP on 2 5/8" Csq. Shoot Pipe at free Point Lay down Csq.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. *Continued on back side*

SIGNATURE J. K. Rawlinson TITLE Agent DATE 29 Mar. 89

TYPE OR PRINT NAME: _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Orig. Signed by
Paul Kautz
Geologist

MAR 29 1989

10. Run Tbg. To CUT of 8 5/8" CSg. Pump 100' Plug (50' in 50' out) (50 SKs.)
11. Pump 100' Plug 400-300' (65 SKs. + -)
12. 10 SKs. Surface Plug.

INSTALL Dry hole marker Clean loc. Rig down.

RECEIVED

MAR 29 1989

OCC
MOBBS OFFICE