

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
OG-765

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Read & Stevens, Inc.	Gross
3. Address of Operator	9. Well No.
P.O. Box 2126, Roswell, New Mexico 88201	2
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>F</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>2130</u> FEET FROM THE <u>West</u> LINE, SECTION <u>15</u> TOWNSHIP <u>10S</u> RANGE <u>33E</u> N.M.P.M.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4193' GR	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/20/72: Notice of Intention to Plug & Abandon
with verbal approval from NMOCC this date

Set cast iron bridge plug at 9500'. Cap with 35' of cement. Fill hole with good mud.

Set 35 sx. plug in 5½" casing stub.

Set 35 sx. plug @ 5222' to 5122'
Set 35 sx. plug @ 3930' to 3830'
Set 56 sx. plug in 8 5/8" casing stub.
Set 80 sx. plug @ 400' to 300'
Set 10 sx. plug @ 10' to 0'

Erect regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe D. Ramey TITLE Agent DATE 3/29/72

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE APR 3 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MARCH 1970

WILSON CONSERVATION COMM.
ROCKY, N. M.