NO. OF COPIES RECEIVE			
			Form C-103
DISTRIBUTION			Supersedes Old
SANTA FE		NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE			Effective 1-1-05
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State X Fee
OPERATOR			5. State Oil & Gas Lease No.
		· 	OG-1204
	SUNDRY	NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS	S FORM FOR PROPOUSE **APPLICATION	NOTICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
		3000 110 00 2517	7. Unit Agreement Name
	GAS WELL	OTHER-	, , , esse signediate realize
2. Name of Operator			8. Form or Lease Name
Cattle-	Land Oil C	OMDARY	Atlantic State
3. Address of Operator			9. Well No.
c/o 0il	Reports &	Gas Services, Box 763, Hobbs, New Mexico	1
4. Location of Well	<del> </del>		10. Field and Pool, or Wildcat
UNIT LETTER G	1	980 FEET FROM THE NOTTH LINE AND 1980 FEET FR	N. Mascalare - SA
ONIT CETTER	· · · · · · · · · · · · · · · · · · ·	FEET FROM THE FEET FR	OM TITTITITITITITITITITITITITITITITITITIT
Tue East		1 TOWNSHIP 10 S RANGE 32 E	
1112	LINE, SECTION_	TOWNSHIP RANGE NMP	** (
		15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		4242.6	Lea
6.	Cl	propriate Box To Indicate Nature of Notice, Report or C	
		PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING			ALTERING CASING PLUG AND ABANDONMENT
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.  CHANGE PLANS  CASING TEST AND CEMENT JQB	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	Completed Opera	COMMENCE DRILLING OPNS.  CHANGE PLANS  CASING TEST AND CEMENT JQB	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a	COMMENCE DRILLING OPNS.  CASING TEST AND CEMENT JQB  OTHER  Ittions (Clearly state all pertinent details, and give pertinent dates, including the complete of	PLUG AND ABANDONMENT X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a	commence drilling opns.  casing test and cement JQB  other  other	PLUG AND ABANDONMENT X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a	commence drilling opns.  casing test and cement job  other  other  ations (Clearly state all pertinent details, and give pertinent dates, including  the operations commenced 3/26/68 and completed  s follows:  75 sx neat cement placed into and across per  4133-89 with top of plug at 3833.	PLUG AND ABANDONMENT X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a	commence drilling opns.  casing test and cement jqb  other  ditions (Clearly state all pertinent details, and give pertinent dates, including the state all pertinent details, and give pertinent dates, including the state of th	PLUG AND ABANDONMENT X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a	commence drilling opns.  casing test and cement Job  other  ctions (Clearly state all pertinent details, and give pertinent dates, including the state of the sta	PLUG AND ABANDONMENT X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a. 1. 2.	commence drilling opns.  casing test and cement Job  other  casing test and cement Job  other  other  other  attons (Clearly state all pertinent details, and give pertinent dates, including the state of plug at 3833.  Cut and pulled 4 1/2" casing at 1727', with 25 sx cement plug set across casing stub. To of plug at 1577'.	PLUG AND ABANDONMENT X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a. 1. 2.	commence drilling opns.  casing test and cement job  other  other	PLUG AND ABANDONMENT X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a. 1. 2. 3.	commence drilling opns.  casing test and cement job  other  attons (Clearly state all pertinent details, and give pertinent dates, including  the operations commenced 3/26/68 and completed  follows:  75 sx neat cement placed into and across per  4133-89 with top of plug at 3833.  Cut and pulled 4 1/2" casing at 1727', with  25 sx cement plug set across casing stub. To  of plug at 1577'.  25 sx cement plug set across 8 5/8" surface  casing shoe with top of plug at 250'.	PLUG AND ABANDONMENT X  ag estimated date of starting any proposed  from the starting and prop
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a. 1. 2. 3. 4.	commence drilling opns.  casing test and cement Job  other  tions (Clearly state all pertinent details, and give pertinent dates, including  nt operations commenced 3/26/68 and completed  follows:  75 sx neat cement placed into and across per  4133-89 with top of plug at 3833.  Cut and pulled 4 1/2" casing at 1727', with  25 sx cement plug set across casing stub. To  of plug at 1577'.  25 sx cement plug set across 8 5/8" surface  casing shoe with top of plug at 250'.  10 sx cement plug set at surface in 8 5/8' of	PLUG AND ABANDONMENT X  ing estimated date of starting any proposed  fris  p
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a. 1. 2. 3. 4.	commence drilling opns.  casing test and cement Job  other  casing test and cement Job  other  ations (Clearly state all pertinent details, and give pertinent dates, including  the operations commenced 3/26/68 and completed  follows:  75 sx neat cement placed into and across per  4133-89 with top of plug at 3833.  Cut and pulled 4 1/2" casing at 1727', with  25 sx cement plug set across casing stub. To  of plug at 1577'.  25 sx cement plug set across 8 5/8" surface  casing shoe with top of plug at 250'.  10 sx cement plug set at surface in 8 5/8' casing with  Steel plate welded over 8 5/8" casing with	PLUG AND ABANDONMENT X  ing estimated date of starting any proposed  fractions  p
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a. 1. 2. 3. 4.	commence drilling opns.  casing test and cement Job  other  casing test and cement Job  other  ations (Clearly state all pertinent details, and give pertinent dates, including  the operations commenced 3/26/68 and completed  follows:  75 sx neat cement placed into and across per  4133-89 with top of plug at 3833.  Cut and pulled 4 1/2" casing at 1727', with  25 sx cement plug set across casing stub. To  of plug at 1577'.  25 sx cement plug set across 8 5/8" surface  casing shoe with top of plug at 250'.  10 sx cement plug set at surface in 8 5/8' casing with  Steel plate welded over 8 5/8" casing with	PLUG AND ABANDONMENT X  ing estimated date of starting any proposed  frig.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a. 1. 2. 3. 4. 5.	commence drilling opns.  casing test and cement Job  other  ations (Clearly state all pertinent details, and give pertinent dates, including  the operations commenced 3/26/68 and completed  follows:  75 sx neat cement placed into and across per  4133-89 with top of plug at 3833.  Cut and pulled 4 1/2" casing at 1727', with  25 sx cement plug set across casing stub. To  of plug at 1577'.  25 sx cement plug set across 8 5/8" surface  casing shoe with top of plug at 250'.  10 sx cement plug set at surface in 8 5/8' of  Steel plate welded over 8 5/8" casing with  steel marker extending 4' above ground level	PLUG AND ABANDONMENT X  ing estimated date of starting any proposed  frig.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a. 1. 2. 3. 4. 5. Mud laden	commence drilling opns.  casing test and cement Job  other  other  casing test and cement Job  other  other	PLUG AND ABANDONMENT X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  7. Describe Proposed or	Abandonmer 3/27/68 a. 1. 2. 3. 4. 5. Mud laden	commence drilling opns.  casing test and cement Job  other  ations (Clearly state all pertinent details, and give pertinent dates, including  the operations commenced 3/26/68 and completed  follows:  75 sx neat cement placed into and across per  4133-89 with top of plug at 3833.  Cut and pulled 4 1/2" casing at 1727', with  25 sx cement plug set across casing stub. To  of plug at 1577'.  25 sx cement plug set across 8 5/8" surface  casing shoe with top of plug at 250'.  10 sx cement plug set at surface in 8 5/8' of  Steel plate welded over 8 5/8" casing with  steel marker extending 4' above ground level	PLUG AND ABANDONMENT X

APPROVED BY RUNY TITLE DATE

TITLE \_

Agent

4/18/68