CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energ linerals and Natural Resources Department

Form C-103

Revised 1-1-89

Same Pc, New Mexico 87504-2088   Same Pc, New Mexico 87504-2088   Sincero Type of Lines	P.O. Box 1980, Hobbs, NM \$8240  OIL CONSERVATION DIVISION P.O. Box 2088			WELL API NO.		
SUNDRY NOTICE OF INTENTION TO:  SUNDRY NOTICE AND REPORTS ON WELLS  (DO NOT USE THIS SCONE POR PROPOSALS TO DRILL OR TO DESPEN OR PULIG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT"  (DO NOT USE THIS SCONE POR PROPOSALS)  1. Typ of Walt:  ONL   ONLY USE THIS SCONE POR SUCH PROPOSALS TO DRILL OR TO DESPEN OR PERMIT"  (The Man of Operator  Amen of Operator  A					5. Indicate Type of Lease	
COONDY USE THIS POWER FOR PROPOSALS TO DRILL OF TO BEEPEN OR PLUG BACK TO A DEFERENCE RESERVOR. USE "APPLICATION FOR SUCH PROPOSALS"	DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE X FEE 6. State Oil & Gas Lesse No.		
2 Name of Operator Amerada Hess Corporation 3 Address of Operator Trawer D, Monument, N.M. 88265 4 Will Location Usik Letter M: 585 Feet From The South Line and 735 Feet From The West Line Section 24 Tromship 11S Range 32E NAMPM Lea Country  Section 24 Township 11S Range 32E NAMPM Lea Country  10. Elevation (Shore whether DP. RKB. KT. GR. dic.)  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CASING TEST AND CEMENT JOB OTHER:  11. Describe Proposed or Completed Operations (Clearly state all pertivent details, and give pertinent data, including estimated data of starting any proposed word, SEE RILE 1103.  Call NMOCD 24 hours before rig-up. Plan to MIRU pulling unit, remove wellhead & install BOP. Release pkr. & TOH w/tbg. strings.  TIH w/CIBP in 3-1/2' csg. & set at 8125'. Dump 20' cement on top CIBP. TIH w/CIBP in 2-7/8" & 3-1/2' csg. at 6000' at	( DO NOT USE THIS FORM FOR PRO DIFFERENT RESER	7. Lease Name or Unit Agreement Name	<b>Z</b>			
2 Nema of Operator Amerada Hess Corporation 3. Address of Operator Drawer D, Monument, N.M. 88265 4. Well Lossian Usik Letter M: 585 Feet From The South Line and 735 Feet From The West Line Section 24 Township 11S Range 32E NMPM Lea County 10. Elevation (Show white Dr. RKER, RT, GR. acc.) 4338' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON NATURE COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS OTHER: OTHE		O'Desa.	ΤΔΙ	d	AM atet2	
1. More of Operator   D., Monument, N.M. 88265   See Proor The   South   Line and   735   Feet Proor The   West   Line	2. Name of Operator		- 171	<u> </u>		-
Drawer D, Monument, N.M. 88265  4. Wall Lossion  Unal Lester M: 585 Feet Proon The South Line and 735 Feet From The West Line  Socion 24 Township 11S Runge 32E NMPM Lea County  10. Elevation (Show whither DC, REE, RT, GR, etc.)  4338' DF  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of sterring any proposed very SEE RULE 1103.  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of sterring any proposed very SEE RULE 1103.  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of sterring any proposed very SEE RULE 1103.  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of sterring any proposed very SEE RULE 1103.  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of sterring any proposed very SEE RULE 1103.  12. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated dates of sterring any proposed very pertinent dates, including estimated dates of sterring any proposed very pertinent dates, including estimated dates of sterring any proposed very pertinent dates. Notice pertinent dates, including estimated dates of sterring any proposed very pertinent dates. Notice pertinent dates, including estimated dates, including estimated dates of sterring any percent pertinent dates. Notice pertinent dates, including estimated date		10n			9. Pool name or Wildow	
Unit Lester M: 585 Feet From The South Line and 735 Feet From The West Line Section 24 Township 11S Range 32E NMPM Lea County (10. Elevation (Show whether DF, RKB, RT, GR, stc.) 4338* DF  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON NOTHER CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON NOTHER:  DOTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  Call NMOCD 24 hours before rig-up.  Plant to MRU pulling unit, remove wellhead & install BOP. Release pkr. & TOH w/tbg. strings. TIH w/CIBP in 3-1/2" csg. & set at 8330'. Dump 20' cement on top CIBP. TIH w/CIBP in 2-7/8" csg. & set at 8125'. Dump 20' cement on top CIBP. Jet cut 2-7/8" & 3-1/2" csg. at ± 6000' & TOH. Cheen to plug across csg. Stubs. Spot 100' cement plug across intermediate shoe. Perf. 8-5/8" csg. at 1510'. Squeeze 100' cement surface plug. Cut off wellhead & dead man anchors. Install dry hole marker, remove all well/is eqpt. & clean location.    Date	Drawer D, Monument, N	.M. 88265				
10. Elevation (Show whether DF, REB, RT, GR, stc.)  4338* DF  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  ALTERING CASING  COMMENCE DRILLING OPNS. PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed word). SEE RULB 1103.  Call NMOCD 24 hours before rig-up.  Plan to MIRU pulling unit, remove wellhead & install BOP. Release pkr. & TOH w/tbg. strings. TIH w/CIBP in 3-1/2" csg. & set at 8330'. Dump 20' cement on top CIBP. Jet cut 2-7/8" & 3-1/2" csg. at + 6000' & 100' cement plug across intermediate shoe. Perf. 8-5/8" csg. at 1510'. Squeeze 100' cement plug across 10-3/4" shoe. Spot 100' cement plug across top of 8-5/8" at 677'. Spot 50' cement surface plug. Cut off wellhead & dead man anchors. Install dry hole marker, remove all well/is eapts. & clean location.  ORIGINAL SIGNED BY JEDRY SENTING.  ORIGINAL SIGNED BY JEDRY SENTING.  ORIGINAL SIGNED BY JEDRY SENTING.  Adm. Svc. Coord.  TILLEPIENDE MO. 505 393-214  TILLEPIENDE MO. 505 393-214		Feet From The Sour	<u>th</u>	Line and 735	Feet From The West Lin	16
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REMEDIAL WORK	Section 24				NMPM Lea County	
TEMPORABILE 103.  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER:  12 Describe Proposed or Completed Operations (Clearly state all partinent details, and give pertinent dates, including estimated date of starting any proposed word) SEE RULE 1103.  Call NMOCD 24 hours before rig-up.  Plan to MIRU pulling unit, remove wellhead & install BOP. Release pkr. & TOH w/tbg. strings. ITH w/CIBP in 3-1/2" csg. & set at 8330'. Dump 20' cement on top CIBP. TIH w/CIBP in 2-7/8" csg. & set at 8125'. Dump 20' cement on top CIBP. Jet cut 2-7/8" & 3-1/2" csg. at 4 6000' & TOH. Circ. hole w/10 PPG plug mud. Spot 35 sks. (100') cement plug across scg. stubs. Spot 100' cement plug across stop at 1510'. Squeeze 100' cement plug across 10-3/4" shoe. Spot 100' cement plug across top of 8-5/8" at 677'. Spot 50' cement surface plug. Cut off wellhead & dead man anchors. Install dry hole marker, remove all well/is eapper for State Unity Country that the information shows symme and complete to the best of my browledge and belief.    Describe Proposed or Completed Operations (Clearly state all partinent dates, including estimated date of starting any proposed comment and partinent dates, including estimated date of starting any proposed comment and the proposed comment of the partinent dates, including estimated date of starting any proposed comment of the partinent dates, including estimated date of starting any proposed comment of the partinent dates, including estimated date of starting any proposed comment of the partinent dates, including estimated date of starting any proposed comment of the partinent dates, including estimated dates of starting any proposed comment of the partinent dates, including estimated dates of starting any proposed comment of the partinent dates, including estimated dates of starting an		'/////A		•		7
NOTICE OF INTENTION TO:    PERFORM REMEDIAL WORK	11. Check A				eport, or Other Data	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:    12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.    12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.    12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.    12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed overly SEE RULE 1103.    10 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed others.    10 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed others.    10 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed others.    10 Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed on the pertinent dates, including estimated date of starting any proposed on the pertinent dates, including estimated date of starting any proposed on the pertinent dates, including estimated dates of starting any proposed on the pertinent dates, including estimated dates of starting any proposed on the pertinent dates, including estimated dates of starting any proposed on the pertinent dates, including estimated dates of starting any proposed on the pertinent dates, including estimated dates of starting any proposed on the pertinent dates, including				•	-	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:    CASING TEST AND CEMENT JOB OTHER:	PERFORM REMEDIAL WORK	PLUG AND ABANDON	X	REMEDIAL WORK	ALTERING CASING	٦
CASING TEST AND CEMENT JOB  OTHER:  OT	TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING		$\exists$
OTHER:  12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  Call NMOCD 24 hours before rig-up. Plan to MIRU pulling unit, remove wellhead & install BOP. Release pkr. & TOH w/tbg. strings. TIH w/CIBP in 3-1/2" csg. & set at 8330'. Dump 20' cement on top CIBP. TIH w/CIBP in 2-7/8" csg. & set at 8125'. Dump 20' cement on top CIBP. Jet cut 2-7/8" & 3-1/2" csg. at ± 6000' & 100' cement plug across csg. stubs. Spot 100' cement plug across csg. stubs. Spot 100' cement plug across intermediate shoe. Perf. 8-5/8" csg. at 1510'. Squeeze 100' cement plug across 10-3/4" shoe. Spot 100' cement plug across top of 8-5/8" at 677'. Spot 50' cement surface plug. Cut off wellhead & dead man anchors. Install dry hole marker, remove all well/Is eqpt. & clean location.  1 bereby certify that the information above in true and complete to the best of my knowledge and bedief.  Adm. Svc. Coord.  Adm. Svc. Coord.  DATE  TILEPHONE NO. 505 393-214  (Chis space for State Use)  ORIGINAL SIGNED BY JETPLY SENTON.	PULL OR ALTER CASING		J			_
Call NMOCD 24 hours before rig-up.  Plan to MIRU pulling unit, remove wellhead & install BOP. Release pkr. & TOH w/tbg. strings. TIH w/CIBP in 3-1/2" csg. & set at 8330'. Dump 20' cement on top CIBP. TIH w/CIBP in 2-7/8" csg. & set at 8125'. Dump 20' cement on top CIBP. Jet cut 2-7/8" & 3-1/2" csg. at ± 6000' & TOH. Circ. hole w/10 PPG plug mud. Spot 35 sks. (100') cement plug across csg. stubs. Spot 100' cement plug across intermediate shoe. Perf. 8-5/8" csg. at 1510'. Squeeze 100' cement plug across 10-3/4" shoe. Spot 100' cement plug across top of 8-5/8" at 677'. Spot 50' cement surface plug. Cut off wellhead & dead man anchors. Install dry hole marker, remove all well/is eqpt. & clean location.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SNONATURE  TYPEOR FRINT NAME  R. L. Wheeler, Jr.  THE Adm. Svc. Coord.  Adm. Svc. Coord.  DATE 6-30-95  TITLE  ORIGINAL SIGNED BY JERREY SEXTONA	OTHER:					
Call NMOCD 24 hours before rig-up.  Plan to MIRU pulling unit, remove wellhead & install BOP. Release pkr. & TOH w/tbg. strings. TIH w/CIBP in 3-1/2" csg. & set at 8330'. Dump 20' cement on top CIBP. TIH w/CIBP in 2-7/8" csg. & set at 8125'. Dump 20' cement on top CIBP. Jet cut 2-7/8" & 3-1/2" csg. at ± 6000' & TOH. Circ. hole w/10 PPG plug mud. Spot 35 sks. (100') cement plug across csg. stubs. Spot 100' cement plug across intermediate shoe. Perf. 8-5/8" csg. at 1510'. Squeeze 100' cement plug across 10-3/4" shoe. Spot 100' cement plug across top of 8-5/8" at 677'. Spot 50' cement surface plug. Cut off wellhead & dead man anchors. Install dry hole marker, remove all well/ls eqpt. & clean location.  Thereby certify that the information above, is true and complete to the best of my knowledge and belief.  SIGNATURE Adm. Svc. Coord.  TITLE Adm. Svc. Coord.  TITLE Adm. Svc. Coord.  TITLE Adm. Svc. Coord.  TITLE DATE 6-30-95  TITLE ORIGINAL SIGNED BY JERREY SEXTONS.	12. Describe Proposed or Completed Operati	ons (Clearly state all pertinent de	tails, an	d give pertinent dates, includ	ing estimated date of starting any proposed	_
SIONATURE Adm. Svc. Coord.  THE PRINT NAME  R. L. Wheeler, Jr.  THE OR PRINT NAME  R. L. Wheeler, Jr.  ORIGINAL SIGNED BY JERRY SEVENA	Call NMOCD 24 hours before Plan to MIRU pulling unit TIH w/CIBP in 3-1/2" csg. csg. & set at 8125'. Dun & TOH. Circ. hole w/10 F 100' cement plug across iplug across 10-3/4" shoe.	t, remove wellhead & set at 8330'.  IP 20' cement on to  PG plug mud. Spot  ntermediate shoe.  Spot 100' cement	Dump p CI 35 Per plu	20' cement on BP. Jet cut 2-; sks. (100') cem f. 8-5/8" csg. a g across top of	top CIBP. TIH w/CIBP in 2-7/8 7/8" & 3-1/2" csg. at ± 6000' ent plug across csg. stubs. S at 1510'. Squeeze 100' cement 8-5/8" at 677'. Spot 50' cem	" pot
(This space for State Use)  ORIGINAL SIGNED BY JERBY SEXTON	SIGNATURE LIVER R. I. Wheel	L.	•	Adm. Svc. Co	DATE	- - -214
······································	(This space for State Use) ORIGIN	AL SIGNED BY JERRY SE) District I supervisor	(TON		DATE JUL 0 5 1995	= ; _

## RECEIVER

JUL . 1995

OFFICE

## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

PISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

CONDITIONS OF APPROXAL, JENANYL COMMENT AND ANALYSIS

## OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 - Revised 10-1-78

	SANTA FE, NEW MEXICO 87501	•
FILE		Sa. Indicate Type of Lease
U.S.O.S.		State X Foe
DERATOR		5. State Oil & Gas Lease No.
or Edulon		B9596
SUNDRY NOTICES.	AND REPORTS ON WELLS	
(00 HOT USE THIS FORM FOR PROPOSALS TO DRILL USE "APPLICATION FOR PERMIT -	OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
1. OIL XX GAB OTHER-		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
		State M "A"
Amerada Hess Corporation  J. Address of Operator		9. Well No.
Drawer D, Monument, New Mexico 88	265	3
4. Location of Well		10. Field and Pool, or Wildcat
V 505	FROM THE South LINE AND 735 FEET F	Moore Walform Pas -
UNIT LETTER , , PEET	FROM THE LINE AND FEET F	THIS THE THEFT WAS
West 24	TOWNSHIP 11S HANGE 32E	
THE LINE, SECTION	TOWNSHIP RANGE HM	(
15.1	Levation (Show whether DF, RT, GR, etc.)	12. County
	4338' DF	Lea
16. Check Appropriate	Box To Indicate Nature of Notice, Report or	Other Data
NOTICE OF INTENTION TO	-	ENT REPORT OF:
NOTICE OF INTENTION IS	3003240.	THE TOTAL OF THE TENT OF THE T
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE ORILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
PULL OR ACTER CASING	OTHER	Well TA'd.
OTHER		
	y state all pertinent details, and give pertinent dates, includ	ling estimated date of starting any proposed
work) SEE RULE 1103.		
5-1-88		
Closed all valves & TA'd well.		
	•	
	·	
18. I hereby certify that the information above is true an	d complete to the best of my knowledge and belief.	
0011100		( 00 00
AIGHED W. C. Wheeler Ja	Supv. Adm. Svc.	6-28-88
	Alf	
ORIGINAL SIGNED BY JEERY SEXTO	NA	
DISTRICT I SUPERVISOR	7171 #	DATE

RECEIVED

**J**UN 3 0 198**9** 

CONTRACTOR