

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-4601	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Southland Royalty Company		Shell State
3. Address of Operator		9. Well No.
1405 Wilco Building, Midland, Texas 79701		2
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>L</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>440</u> FEET FROM		Inbe-Penn.
THE <u>West</u> LINE, SECTION <u>19</u> TOWNSHIP <u>11-S</u> RANGE <u>34-E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4211.0 G.L.		Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set 35' plug @ 9875'
2. Set 25 sk plug @ 5½" stub @ approximately 4500'
3. Set 50 sk plug in and out of 8 5/8" shoe @ 3956'
4. 35 sk plug @ 8 5/8" <sup>stab</sup> ~~stab~~ approximately 1100'
5. 35 sx in and out of 11 3/4" @ 357'
6. 10 sx @ surface

Clean location and install well marker.

*100' plugs*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Allen C. Goodrich TITLE Dist. Prod. Supt. DATE 1-10-73

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE JAN 12 1973  
CONDITIONS OF APPROVAL, IF ANY: