

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>E-7324</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>State</b>
9. Well No. <b>5</b>
10. Field and Pool, or Wildcat <b>Inbe Permo Penn</b>
12. County <b>Lea</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator <b>Clar-Don Products Company</b>
3. Address of Operator <b>c/o Oil Reports &amp; Gas Service, Inc., Box 763, Hobbs, N. M. 88240</b>
4. Location of Well UNIT LETTER <b>C</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>1980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>24</b> TOWNSHIP <b>10 S</b> RANGE <b>33 E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>4199 RKB</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Set Cast Iron Bridge Plug @ 9800, cap with 35 cement on top.  
Shot 5 1/2 casing @ 4077 and 3846 and pulled  
Spot 100' cement plug across 5 1/2 stub @ 3846 (40 sks - 3796-3896)  
Shot 9 5/8 casing @ 1485, 1369 and 1249 and pulled  
Spot 100' cement plug across 9 5/8 stub (60 sks - 1199-1299)  
Spot 100' cement plug across 13 3/8 shoe @ 406 (356-456)  
10 sacks at surface. Install dry hole marker.  
Mud between all plugs.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Donna Miller* TITLE Agent DATE 1/31/74

APPROVED BY *Eddie W. Dean* TITLE OIL & GAS INSPECTOR DATE 1/31/74

CONDITIONS OF APPROVAL, IF ANY: