

N. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. SEE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
1. Name of Operator BABER WELL SERVICING CO.		5. State Oil & Gas Lease No.
2. Address of Operator P. O. BOX 1772, HOBBS, NEW MEXICO 88240		7. Unit Agreement Name
3. Location of Well UNIT LETTER O 1980' FEET FROM THE East LINE AND 660' FEET FROM THE South LINE, SECTION 7 TOWNSHIP 11 S RANGE 37 E N.M.P.M.		8. Farm or Lease Name ANDERSON 7
15. Elevation (Show whether DF, RT, GR, etc.) GL 3991.9		9. Well No. #1
12. County LEA		10. Field and Pool, or Wildcat WILDCAT

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> OTHER <input type="checkbox"/>
---	---	---	---

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 4800' w/50' of cement on top.
Pull 4 1/2" casing where free.
Put 100' plug in & out at top of stub. Put 100' plug in & out at top of 8-5/8" stub at 1235'. Put 100' plug in & out of bottom 12-3/4' surface pipe. Put 10 Sx. plug at surface and install marker.
Clean up location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Aug. John* TITLE PRESIDENT DATE 5/2/78

APPROVED BY *Dist 1, Supv.* TITLE DATE 5/2/78

CONDITIONS OF APPROVAL, IF ANY:

Expires 11/3/78