

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Allen K. Trobaugh		8. Farm or Lease Name Wood
3. Address of Operator 106 Wall Towers West, Midland, Texas 79701		9. Well No. 2
4. Location of Well UNIT LETTER C 1980 FEET FROM THE West LINE AND 660 FEET FROM THE North LINE, SECTION 29 TOWNSHIP 9S RANGE 34E NMPM.		10. Field and Pool, or Wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4283 GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugs as follows:

CIBP at 9800' w/20' cement(perfs 9841'-9850')
 100' plug at stub of 5½" casing
 100' plug at 5420' (T/Glorietta)
 100' plug in and out of 8-5/8" shoe at 3990'
 100' plug at stub of 8-5/8" casing
 100' plug in and out of 12-3/4" shoe at 364'
 10 sack plug in top
 Install dry hole marker

* 100' plug at top of salt @ ± 2120', if not behind Pipe

Expires 7/6/77

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Allen K. Trobaugh TITLE Operator DATE 7/2/76

Orig. Signed by
John Runyan
Geologist

APPROVED BY _____ TITLE _____ DATE 5/6

CONDITIONS OF APPROVAL, IF ANY: