

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No. 291-310 (E-26)
& 291-312 (OG-1402)

7. Lease Name or Unit Agreement Name

Lea "OG" STATE

8. Well No.

1

9. Pool name or Wildcat

N. Bagley Farm Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

TEAM EXPLORATION

3. Address of Operator

310 W. Illinois, Suite 220, Midland, TX 79701

4. Well Location

Unit Letter K : 1980 Feet From The West Line and 1980 Feet From The South Line

Section 9

Township 11S

Range 33E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU Carr Well Service.

2. RIH w/packer. Attempt to pump. If unable to pump set OH plug; if able to pump squeeze off.

3. Run Three Point and shoot off 5-1/2" 15.5# casing (est. 5000' ±).

4. GIH with 2-3/8" tbg and pump 100' plug (50' in & 50' out of 5-1/2" casing stub and tag.

5. Set 100' plug 50' in, 50' out 8-5/8" casing shoe.

6. Shoot and pull 800' (est) of 8-5/8" 24# casing.

7. GIH with tbg and pump 100' cement plug 50' in, 50' out of 8-5/8" casing stub and 13-3/8" casing shoe.

8. Pump 100' plug across 13-3/8" casing shoe and tag.

9. Pump 10 sx surface plug and erect dry hole marker.

Load hole w/mud consisting 10 lb brine w/25 lb gel/barrel

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donald A. Turner

TITLE President, Team Expl. DATE 2-08-89

TYPE OR PRINT NAME Donald A. Turner

TELEPHONE NO. 915/682-3418

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

FEB 16 1989

RECEIVED

FEB 13 1989

OCD
HOBBS OFFICE

NOT RECORDED
FEB 13 1989
FBI