

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1100 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-10130
7. Lease Name or Unit Agreement Name Murphy "A" State
8. Well No. 1
9. Pool name or Wildcat Inbe-Permo-Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 4205.6

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Kaiser Francis Oil Co. Tierra Exploration Inc.	3. Address of Operator P.O. Box 5057, Hobbs, NM 88241 (505) 392-2112
4. Well Location Unit Letter J : 1980 Feet From The East Line and 1980 Feet From The South Line Section 24 Township 10S Range 33E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 4205.6	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

1. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot 35 sx plug from 9600' (perfs @ 9878' - 9882') tag plug.
2. Load hole with Gelled Brine water.
3. Set 25 sx plug @ 8500'.
4. Shoot and pull 5½" casing.
5. Spot 40 sx plug 50' in & 50' out of 5½" csg stub.(tag)
6. Spot 40 sx plug @ 4060' - 3960'.
7. Shoot and pull 8-5/8" casing.
8. Spot 100' plug across 8-5/8" csg stub 50' in & 50' out.(tag)
9. Spot 75 sx plug from 425' - 325'.
10. Spot 25 sx plug @ surface.
11. Well on cap & install dry hole marker.

THE OPERATOR MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joe T. Janica TITLE President DATE 9/1/93
TYPE OR PRINT NAME Joe T. Janica TELEPHONE NO. 505-392-2112

(This space for State Use) **ORIGINAL SIGNED BY JERRY SEXTON**
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE SEP 02 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 01 1993

**COB HODSS
OFFICE**