- -		UL CONS. COMMISSION
	3.42.54 	0X 1980 SW MEXICO 88240
	TED STATES / C DU	HIGH HIGH HIGH HIGH HIGH HIGH HIGH HIGH
	ROFCHEINTERIOR	Expires: March 31, 1993
BUREAU OF LAND MANAGEMENT		5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS		NM 072477 6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to dr Use "APPLICATION FO	IL or to deepen on teentry to a different reservoir. R PERMBBS, ton such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
I. Type of Well Oil Gas Well Well Other		8. Well Name and No.
2. Name of Operator		Helen #1
Tipperary Oil and Gas Corporation 3. Address and Telephone No. (015) (02, 5202)		9. API Well No.
3. Address and Telephone No. 800 N. Marienfeld, Suite 100, Midland, Tx 79701 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		30-025-22440 10. Field and Pool, or Exploratory Area North Bagloy (Louor
Unit Letter N., Sec. 17, T11S, R33E		North Bagley (Lower 11. County or Parish, State Penn
660' FSL and 1980' FWL	, 1115, K55E	LEA
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	· · · · · · · · · · · · · · · · · · ·
Notice of Intent		Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair	Water Shut-Off Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
	I pertinent details, and give pertinent dates, including estimated date of startin al depths for all markers and zones pertinent to this work.)*	ig any proposed work. If well is directionally drilled,
per 100 bbls water. S and pull as much as por 1/2 out of the stub. out of 8 5/8" shoe (37 (<u>+</u> 1000'). Set 100' pl	400'. Pump 50sx cement through 5250'. Circulate hole with m 5pot 100' plug (10sx) at 6250'. 5ssible (\pm 5000'). Set 100' plug WOC and tag. Set 100' plug (3 728'). Cut 8 5/8" casing and p Lug (40sx) 1/2 in and 1/2 out o 3/8" shoe (383'). Set 10 sx p	ud mixed at 25sx gel Cut 4 1/2" casing g (20sx) 1/2 in and 0sx) 1/2 in and 1/2 oull as much as possible f stub. Set 100' lug at surface. Weld
		Norski se Stateniji Norski se se Norski se Stateniji
		(* 5.) Same (* 1997) 1787
		And a second sec
14. I hereby certify that the foregoing is true and correct Signed 12. The started	Engineer Title	12/13/94
		hoe, @ 878" stub,
or representations as to any matter within its jurisdiction.	*See Instruction on Reverse Side	

RECEVED

JAN 1 7 1995

UCD HOBBS, OFFICE

· 建氯化物物 一般的 化化学 化化学 化化学 化化学 化化学 化化学 化化学