			•
NO. OF COPIES RECEIVED	- ,		
DISTRIBUTION			Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CON	SERVATION COMMISSION	C-102 and C-103
FILE		SERVATION COMMISSION	Effective 1-1-65
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE	7		State X Fee
OPERATOR			5. State Oil & Gas Lease No.
			0G-5845
SUND (DO NOT USE THIS FORM FOR F	RY NOTICES AND REPORTS ON ROPOSALS TO DRILL OR TO DEEPEN OR PLUG	WELLS	
1.	FORM C-101) FOR SU	CH PROPOSALS.}	7. Unit Agreement Name
OIL X GAS WELL 2. Name of Operator	OTHER-		
·			8. Farm or Lease Name
Sun Oil Compan 3. Address of Operator	<u>у</u>		N. M. Broseco State
P 0 Roy 1861	Midland, Texas 79701		9. Well No.
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTERC	660 FEET FROM THE North	1980	Vada Penn (Rough C)
		FEET FROM	
THE West LINE, SEC	TION 21 TOWNSHIP 10-S	RANGE 34-E NMPM.	
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
	4221 DF	-1, w, on, e.e.,	Lea
16.			
NOTICE OF	Appropriate Box To Indicate I	1	er Data REPORT OF:
P5950014 P5450144 W	<u></u>		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	. —	COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
F=1	PLUG AND ABANDON	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB	
TEMPORARILY ABANDON	. —	COMMENCE DRILLING OPNS.	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	CHANGE PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER	PLUG AND ABANDONMENT
OTHER 17. Describe Proposed or Completed (work) SEE RULE 1103. Casi	CHANGE PLANS Departions (Clearly state all pertinent detong Puller: C. E. Knight	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, including	PLUG AND ABANDONMENT
other 17. Describe Proposed or Completed (work) SEE RULE 1703. Casi 6-28-71 Spotted 25 sk	Operations (Clearly state all pertinent det ng Puller: C. E. Knight cement plug 9860-9960.	other ails, and give pertinent dates, including & Co., Box 86, Snyder,	PLUG AND ABANDONMENT X
OTHER 17. Describe Proposed or Completed (work) SEE RULE 1103. Casi 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9	Operations (Clearly state all pertinent det ng Puller: C. E. Knight cement plug 9860-9960.	commence drilling opns. CASING TEST AND CEMENT JQB other ails, and give pertinent dates, including & Co., Box 86, Snyder, The Spotted 25 sk plug.	PLUG AND ABANDONMENT X
other 17. Describe Proposed or Completed (work) SEE RULE 1103. Casi 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885.	Operations (Clearly state all pertinent det ng Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud.	commence drilling opns. CASING TEST AND CEMENT JQB other ails, and give pertinent dates, including & Co., Box 86, Snyder, The Spotted 25 sk plug.	PLUG AND ABANDONMENT X
other 17. Describe Proposed or Completed (work) SEE RULE 1703. Casi 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885. 7/1-2/71 Shoot and pu	operations (Clearly state all pertinent det ng Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud. 11 5½" casing from 7494.	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, including & Co., Box 86, Snyder, T Spotted 25 sk plug. Rig up to pull casing.	PLUG AND ABANDONMENT X estimated date of starting any propose exas
other 17. Describe Proposed or Completed (work) SEE RULE 1103. Casi 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885. 7/1-2/71 Shoot and pu 7-5-71 Spot plugs: 2	Operations (Clearly state all pertinent det ng Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud.	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, including & Co., Box 86, Snyder, T Spotted 25 sk plug. Rig up to pull casing.	PLUG AND ABANDONMENT X estimated date of starting any propose exas
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Comports) Casi 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885. 7/1-2/71 Shoot and put 7-5-71 Spot plugs: 2	Operations (Clearly state all pertinent det ng Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud. 11 5½" casing from 7494. 5 sks 7460-7525, 50 sks	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, including & Co., Box 86, Snyder, T Spotted 25 sk plug. Rig up to pull casing.	PLUG AND ABANDONMENT Extimated date of starting any propose
other 17. Describe Proposed or Completed (work) SEE RULE 1103. Casi 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885. 7/1-2/71 Shoot and pu 7-5-71 Spot plugs: 2	Operations (Clearly state all pertinent det ing Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud. 11 5½" casing from 7494. 5 sks 7460-7525, 50 sks 4 clear location.	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, including & Co., Box 86, Snyder, T Spotted 25 sk plug. Rig up to pull casing.	PLUG AND ABANDONMENT X estimated date of starting any propose exas
other 17. Describe Proposed or Completed (work) SEE RULE 1103. 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885. 7/1-2/71 Shoot and pu 7-5-71 Spot plugs: 2 Set marker and	Operations (Clearly state all pertinent det ing Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud. 11 5½" casing from 7494. 5 sks 7460-7525, 50 sks 4 clear location.	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, including & Co., Box 86, Snyder, T Spotted 25 sk plug. Rig up to pull casing.	PLUG AND ABANDONMENT X estimated date of starting any propose exas
other 17. Describe Proposed or Completed (work) SEE RULE 1703. 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885. 7/1-2/71 Shoot and pu 7-5-71 Spot plugs: 2 Set marker and Pipe left in h	Operations (Clearly state all pertinent det ing Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud. 11 5½" casing from 7494. 5 sks 7460-7525, 50 sks 4 clear location.	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, including & Co., Box 86, Snyder, T Spotted 25 sk plug. Rig up to pull casing.	PLUG AND ABANDONMENT X estimated date of starting any propose exas
OTHER 17. Describe Proposed or Completed (work) SEE RULE 1103. 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885. 7/1-2/71 Shoot and pu 7-5-71 Spot plugs: 2 Set marker and Pipe left in h 13 3/8 8 5/8	Operations (Clearly state all pertinent det ing Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud. 11 5½" casing from 7494. 5 sks 7460-7525, 50 sks 4 clear location.	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, including & Co., Box 86, Snyder, T Spotted 25 sk plug. Rig up to pull casing.	PLUG AND ABANDONMENT Extimated date of starting any propose
other 17. Describe Proposed or Completed (work) SEE RULE 1703. 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885. 7/1-2/71 Shoot and pu 7-5-71 Spot plugs: 2 Set marker and Pipe left in h	Operations (Clearly state all pertinent det ing Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud. 11 5½" casing from 7494. 5 sks 7460-7525, 50 sks of clear location.	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, including & Co., Box 86, Snyder, T Spotted 25 sk plug. Rig up to pull casing.	PLUG AND ABANDONMENT Extimated date of starting any propose
OTHER 17. Describe Proposed or Completed (work) SEE RULE 1103. 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885. 7/1-2/71 Shoot and pu 7-5-71 Spot plugs: 2 Set marker and Pipe left in h 13 3/8 8 5/8	Operations (Clearly state all pertinent det ing Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud. 11 5½" casing from 7494. 5 sks 7460-7525, 50 sks clear location.	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, including & Co., Box 86, Snyder, T Spotted 25 sk plug. Rig up to pull casing.	PLUG AND ABANDONMENT X estimated date of starting any propose exas
OTHER 17. Describe Proposed or Completed (work) SEE RULE 1103. 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885. 7/1-2/71 Shoot and pu 7-5-71 Spot plugs: 2 Set marker and Pipe left in h 13 3/8 8 5/8	Operations (Clearly state all pertinent det ing Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud. 11 5½" casing from 7494. 5 sks 7460-7525, 50 sks clear location.	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, including & Co., Box 86, Snyder, T Spotted 25 sk plug. Rig up to pull casing.	PLUG AND ABANDONMENT Extimated date of starting any propose
OTHER 17. Describe Proposed or Completed (work) SEE RULE 1103. 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885. 7/1-2/71 Shoot and pu 7-5-71 Spot plugs: 2 Set marker and Pipe left in h 13 3/8 8 5/8	Operations (Clearly state all pertinent det ing Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud. 11 5½" casing from 7494. 5 sks 7460-7525, 50 sks clear location.	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, including & Co., Box 86, Snyder, T Spotted 25 sk plug. Rig up to pull casing.	PLUG AND ABANDONMENT Extimated date of starting any propose
OTHER 17. Describe Proposed or Completed (work) SEE RULE 1103. 6-28-71 Spotted 25 sk 6-29-71 Run tbg. to 9 6-30-71 TOC @ 9885. 7/1-2/71 Shoot and pu 7-5-71 Spot plugs: 2 Set marker and Pipe left in h 13 3/8 8 5/8	Operations (Clearly state all pertinent det ing Puller: C. E. Knight cement plug 9860-9960. 960; did not touch plug. Load hole with 9.5# mud. 11 5½" casing from 7494. 5 sks 7460-7525, 50 sks clear location.	commence drilling opns. casing test and cement Jqb other ails, and give pertinent dates, including & Co., Box 86, Snyder, T Spotted 25 sk plug. Rig up to pull casing.	PLUG AND ABANDONMENT Extimated date of starting any propose

	_	and complete to the best of my knowledge and belief.	
SIGNED	RWThy hes	TITLE Proration Clerk	DATE July 6, 1971
	2 00		

CONDITIONS OF APPROVAL, IF ANY:

TITLE OIL & GAS INSPECTOR

DATE APR 26 1972

RECEIVED

JUL 7 1971 OIL CONSERVATION COMM. ROBLE N. M.