

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
OG 5338

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Pennzoil Company	8. Name of Lease Name Harris State
3. Address of Operator P. O. Drawer 1828 - Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1830</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>11-S</u> RANGE <u>34-E</u> NMPM	10. Field and Pool, or Wildcat Inbe Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4199.4 G.L.	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-20-75 Perforated, acidized and tested zones 9593-95', 9598-9600', 9656-58',
11-01-75 9736-42' & 9778-88'. No shows of oil, gas or water.

Propose to plug and abandon as follows:

Set C.I. Bridge Plug @ 9400'
Set 100' cement plug @ stub of 5 1/2" casing. Cement top by temperature log 8200'.
Set 100' cement plug across bottom of 8 5/8" casing set @ 3995'.
Set 100' cement plug across stub of 8 5/8" casing. Cement top by temperature log 2235'. ~~* TOP OF ANHYDRITE~~ 1967' MUST BE ISOLATED
Set 100' cement plug across bottom of 13 3/8" casing set @ 365'.
Set 10' cement plug in top of 13 3/8" casing.

Erect dry hole marker and clean up location.

SET 100' PLUG AT 7700
SET 100' PLUG AT 5450
HOLE CAPPED W/ MUD

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Production Manager</u>	DATE <u>November 3, 1975</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>NOV 6 1975</u>
CONDITIONS OF APPROVAL IF ANY:		