

10. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p>
<p>1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Salt Water Disposal</u></p>		<p>5. State Oil & Gas Lease No.</p>
<p>2. Name of Operator <u>Tenneco Oil Company</u></p>		<p>7. Unit Agreement Name</p>
<p>3. Address of Operator <u>P.O. Box 1031 Midland, Texas 79701</u></p>		<p>8. Perm or Lease Name <u>Mounsey</u></p>
<p>4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>14</u> TOWNSHIP <u>9S</u> RANGE <u>84E</u> NMPM.</p>		<p>9. Well No. <u>2</u></p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) <u>4226 DF</u></p>		<p>10. Field and Pool, or Wildcat <u>Yoda Basin East</u></p>
<p>12. County <u>Lee</u></p>		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pump 50 sx cement plug below permanent Packer
 2. Cut 8 5/8" casing at 1000'± and recover casing
 3. Place cement plug 50' on either side of 8 5/8" stubb.
 4. Place 50 sx cement plug at surface.
 5. Erect dry hole marker.
- 2500 201000 13 3/4 sh

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. M. Williams TITLE Prod. Engr DATE 4-10-69

APPROVED BY [Signature] TITLE [Signature] DATE APR 10 1969

CONDITIONS OF APPROVAL, IF ANY: