

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-22577
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-5011

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Dwight A. Tipton
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 755, Hobbs, NM	7. Lease Name or Unit Agreement Name Graham "C" State Com
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>17</u> Township <u>11S</u> Range <u>33E</u> NMPM Lea County	8. Well No. 1
9. Pool name or Wildcat N. Bagley Permo Penn	

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug & abandon as follows:

Set cast iron bridge plug at 8500 & cap w/35' cement
Load hole with mud
Cut & pull 4 1/2" casing from 5000
Spot 100' plug across 4 1/2" casing stub
Cut & Pull 8 5/8" casing from 900
Spot 100' plug across 8 5/8" casing stub
Spot 100' plug across 11 3/4" casing shoe at 410
Set 10 sack plug at surface with regulation marker.
Clean & Level location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Holler TITLE Agent DATE 3-14-91
TYPE OR PRINT NAME Donna Holler TELEPHONE NO. 393-2727

This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

ROVED BY _____ TITLE _____ DATE _____

ITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

1991