

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
3. Address of Operator		9. Well No.
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <input type="checkbox"/> FEET FROM THE <input type="checkbox"/> LINE AND <input type="checkbox"/> FEET FROM		
THE <input type="checkbox"/> LINE, SECTION <input type="checkbox"/> TOWNSHIP <input type="checkbox"/> RANGE <input type="checkbox"/> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

As follows:

1-22-54 Set Casing 950' & Set 35 sx cmt plug from 952' to 9545'
Set 5" Csg. 4024', 504', 521', 4710', 4246- recovered
csg from 4346'. Shot 8 3/8" Csg. 1450' recovered.
Set 6 sx cmt plug from 424' to 4199'.
Set 70 sx cmt plug from 407' to 3891'.
Set 60 sx cmt plug from 387' to 366'.
Set 70 sx cmt plug from 341' to 197'.
Set 10 sx cmt plug from 15' to 0'.

hole was circulated with all plugs set w/ brine mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Gene Milford</u>	TITLE <u>Agent</u>	DATE <u>1-21-54</u>
APPROVED BY <u>Walter E. Kegg</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		