

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instruction on
reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		SEP 6 10 40 AM '91	
2. NAME OF OPERATOR PENROC OIL CORPORATION		CARLOS J. GURROE AREA HEADQUARTERS	
3. ADDRESS OF OPERATOR P.O. Box 5970, Hobbs, NM 88241		8. FARM OR LEASE NAME Midwest "G" Fed Com	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter F, 1980' FN & W Line		9. WELL NO. 1	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, OR, etc.)	
10. FIELD AND POOL, OR WILDCAT Vada Penn		11. SEC., T., R., M., OR BLE. AND SUBST. OR AREA Sec 31, T4S, R34E	
12. COUNTY OR PARISH LEA		13. STATE NM	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANE ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS* (Clearly write all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Rig up well servicing rig. Pull rods & pump. Install BOP & pull tbg.
Run free point. Set CIAP @ 9700'. Spot 50' cement on top of the plug.
Cut and pull 5 1/2" csg. (approx 7000'). TTH w/ tbg and spot 100'
cement plug (50' in & out). Tag plug. Spot 100' cement plug
@ base of 8 5/8" @ 4019' (50' in & out) Tag plug. Spot
100' cement plug @ base of 11 3/4" @ 385' - (50' in & out)
Tag plug. Spot 50' cement plug @ surface. Install dryhole
marker. Clean and re-seed location. @

* Circulate hole w/ 4" gelled brine. Same fluid between plugs
** Notify BLM office - Hobbs - 24 hours prior to starting work.

18. I hereby certify that the foregoing is true and correct

SIGNED Phaedra A. Perche TITLE PRESIDENT

DATE SEPT. 5, 1991

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 9/9/91

*See Instructions on Reverse Side