

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator BTA OIL PRODUCERS		8. Farm or Lease Name Myrtle 689 Ltd.
3. Address of Operator 104 South Pecos Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER "I" 1980 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 31 TOWNSHIP 11-S RANGE 33-E NMPM.		10. Field and Pool, or Wildcat North Bagley, Penn.
15. Elevation (Show whether DF, RT, GR, etc.) 4297 G.R.		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Call NMOCC Hobbs, 505-393-6161 - 24 hrs. in advance of plugging.

1. Cut & Recover 5-1/2" csg. Csg collapsed @ 4691'.
2. Spot 300 sx cmt @ 5-1/2" csg stub.
3. Set 50 sx cmt @ 3735'.
4. Cut & Rec 8-5/8" csg.
5. Set 100 sx cmt @ 8-5/8" Stub.
6. Set 100 sx cmt @ 385'
7. Set 10 sx cmt @ Surface.
8. Install Dry Hole Marker.

Approved 8:00 AM. 7-9-75 By Les Clements.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Bob Newland</u> Orig. Signed by John Runyan Geologist	TITLE <u>Regulatory Supervisor</u>	DATE <u>7/14/75</u>
APPROVED BY _____	TITLE _____	DATE <u>JUL 17 1975</u>
CONDITIONS OF APPROVAL, IF ANY:		