

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator MONSANTO COMPANY	5. State Oil & Gas Lease No. K-6802
3. Address of Operator 1330 Midland NBT, Midland, Tx. 79701	7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>J</u> , <u>2086</u> FEET FROM THE <u>South</u> LINE AND <u>1986</u> FEET FROM THE <u>East</u> LINE, SECTION <u>19</u> TOWNSHIP <u>10S</u> RANGE <u>34E</u> NMPM.	8. Form or Lease Name State "L"
	9. Well No. 2
	10. Field and Pool, or Wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4217 KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set cast iron bridge plug @ 8950'. Set 35' cement on top.
Cut 5 1/2" csg. at 7500'±. Pull casing. Circulate 9.5# mud.
Set 25 Sx. (100') plug 50'in and 50'out of 5 1/2" cut stub.
Set 25 Sx. (100') plug 50' in and 50' out of 8 5/8" shoe at 3993'.
Cut 8 5/8" casing where free. Pull csg. Circulate 9.5# mud.
Set 25 Sx. (100') plug 50' in and 50' out at 8 5/8" cut stub.
Set 100' plug 50' in and 50' out at 11 3/4" shoe at 360'.
Set 10 Sx. plug at surface. Set marker.

RECEIVED
JUL 24 1980
JUL 24 1980
JUL 24 1980
JUL 24 1980

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Regional Prod. Manager

DATE 7/22/80

Orig. Signed by
Jerry Sexton

APPROVED BY Dist. J. Supp.
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUL 24 1980