

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. O&G 5201

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name None	
2. Name of Operator Sage Energy Company	8. Farm or Lease Name Sinclair-State	
3. Address of Operator P. O. Drawer 3068, Midland, Texas 79702	9. Well No. 1	
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>12</u> TOWNSHIP <u>9S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat Bar "U" Penn (Bough "C")	
15. Elevation (Show whether DF, RT, GR, etc.) 4418 GL	12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	SUBSEQUENT REPORT OF:  REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set Cast Iron Bridge Plug with 35sx cement at 9080'.  
Cut 5½" at 3974', could not pull.  
Spot 70 sx plug at 4040 to 3400'.  
Shot 5½" off at 3044', 90 jts pulled.  
50 sx plug at 3080'.  
Cut 8 5/8" at 400'.  
Recovered 9 jts, 400'.  
Spot 90 sx plug at 8 5/8" stub.  
Spot 70 sx plug at 13 3/8" shoe.  
10 sx plug at surface and set parker. P&A 4-11-85.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Francis Halypot</u>	TITLE <u>Production Clerk</u>	DATE <u>April 23, 1985</u>
APPROVED BY <u>Jack Griffin</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>JAN 09 1989</u>
CONDITIONS OF APPROVAL, IF ANY:		