

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.
 NEW MEXICO OIL CONSERVATION COMMISSION
 JUN 4 2 20 PM '69

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. -
7. Unit Agreement Name -
8. Farm or Lease Name Schmidt
9. Well No. 1
10. Field and Pool, or Wildcat Vada
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT..." (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ GAS ☐ OTHER- Dry Hole

2. Name of Operator
Charles B. Read

3. Address of Operator
P.O. Box 2126, Roswell, New Mexico 88201

4. Location of Well
UNIT LETTER H 1980 FEET FROM THE North LINE AND 510 FEET FROM
THE East LINE, SECTION 10 TOWNSHIP 9S RANGE 34E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
4242.5' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To set 25 sx. plug 9660-9760'
 To set 25 sx. plug 8100-8200'
 To set 25 sx. plug 7720-7820'
 To set 25 sx. plug 5300-5400'
 To set 25 sx. plug 4100-4000'

To cut and pull 8 5/8" casing

To set 25 sx. plug in stub of 8 5/8" csg., 50' in and 50' out
 To set 25 sx. plug 350-450'
 To set 10 sx. plug 0-10'

To install dry hole marker.
 To clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 6/2/69

APPROVED BY [Signature] TITLE State Engineer DATE 6/2/69

CONDITIONS OF APPROVAL, IF ANY: