

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-9380
7. Unit Agreement Name
8. Farm or Lease Name New Mexico 'AQ' St. NCT-6
9. Well No. 1
10. Field and Pool, or Wildcat Inbe Permo Penn
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator TEXACO Inc.
3. Address of Operator P.O. Box 728, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER N , 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 10-S RANGE 33-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4,212' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TEXACO Inc. has completed the following work on subject well:

1. Pulled production equipment.
2. Mud up well bore.
3. Spotted 40 sx cement plug in 4-1/2" casing 9835-9405'.
4. Shot 4-1/2" casing at 4696' and pulled.
5. Spot 30 sx cement plug from 4739 to 4605'.
6. Spot 30 sx cement plug from 3956 to 3850'.
7. Spot 10 sx cement plug at surface.
8. Install 4" dry hole marker extending 4' above ground level.
9. Clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE **Assistant District Superintendent** DATE **April 12, 1971**

APPROVED BY *Nathan E. Olegg* TITLE **OIL & GAS INSPECTOR** DATE **DEC 22 1971**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 13 1971

**OIL CONSERVATION COMM.
HOBBS, N. M.**