

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
P.O. Box 1980
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other Temporarily Abandoned Oil Well

2. Name of Operator

Discovery Operating, Inc.

3. Address and Telephone No.

(915) 683-5203
800 N. Marienfeld, Suite 100, Midland, TX 79701

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL & 1980' FEL, Section 5, T-9-S, R-35-E

5. Lease Designation and Serial No.

NM71790

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Wolf Federal No. 1

9. API Well No.

10. Field and Pool, or Exploratory Area

Vada Penn

11. County or Parish, State

Lea County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Proposed P&A

1. Pump 20 sack plug on top of CIBP @ 9645'.
2. Load hole with 9.5#/gal. mud.
3. Cut off 5½" casing @ free point (top of cement @ 8640') and pull same.
4. Spot 100' plug (25 sacks) across 5½" casing stub (50' in and 50' out).
5. Spot 100' plug (35 sacks) across 8 5/8" casing shoe @ 4110' - 4010' (50' in and 50' out).
6. Spot 100' plug (35 sacks) at 820' - 720' (top of salt).
7. Spot 100' plug (35 sacks) at 422' - 322' (50' in and 50' out).
8. Spot 10 sack plug at surface.
9. Cut off wellhead and weld on marker joint.

Anticipated plugging date is 8-31-96

14. I hereby certify that the foregoing is true and correct

Signed *W. Jeffrey Drake*

Title Vice-President

(This space for Federal or State office use)

Approved by *David A. Glass*

Title PETROLEUM ENGINEER

Conditions of approval, if any:

**SEE ATTACHED FOR
CONDITIONS OF APPROVAL**

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BUREAU OF LAND MGMT
HOBBS, NM
Jul 31 2 01 PM '96
RECEIVED
1/30/96

AUG 02 1996