

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 073791

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 3

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Vada Penn

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 3, T9S, R35E

12. COUNTY OR PARISH

Lea

13. STATE

N. M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Coquina Oil Corporation

3. ADDRESS OF OPERATOR

200 Bldg. of Southwest, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

1980' FWL & 660' FNL of Section 3.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

G.L. 4173', K.B. 4184'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

The subject well has ceased to produce oil in commercial quantities and it is our intent to plug and abandon subject well in the following manner:

1. Pull tubing
2. Set 5 1/2" 17# CIBP @ \pm 9700'. Collars at 9613', 9646+', 9680', 9714-' and 9746+'.
3. Run Free Point, cut off and lay down 5 1/2" casing.
4. Run Free Point, cut off and lay down 8 5/8" casing.
5. Go in hole with tubing to spot following plugs:

Plug No.	Ft.	Sx.	From/To
1	75	10	9700 - 9625 on top of C.I.B.P
2	100	30	Top of 5 1/2" stub
3	100	30	5400 - 5300'
4	100	30	4100 - 4000' across intermediate casing shoe
5	100	35	Top of 8 5/8" stub
6	100	75	425 - 325'
7		10	At surface

Load hole with mud between plugs.

Verbal approval received from Mr. Brown - U.S.G.S., Hobbs, New Mexico, on 11-2-73.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Superintendent

DATE 11-2-73

J. L. Berry

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY: