

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator The Superior Oil Company	8. Farm or Lease Name Levinson
3. Address of Operator P.O. Box 71 Conroe, Texas 77301	9. Well No. 1
4. Location of Well UNIT LETTER J, 1980 FEET FROM THE South LINE AND 2130 FEET FROM THE East LINE, SECTION 22 TOWNSHIP 9S RANGE 34E NMPM.	10. Field and Pool, or Wildcat Vada (Penn)
15. Elevation (Show whether DF, RT, GR, etc.) KB-4240' GL-4228'	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Fill hole with mud laden fluid.
2. Equalize 75 sack cement plug across perforations.
3. Recover 5-1/2" casing. Set at 9950'. Top of cement @ 8600'.
4. Spot 35 sack cement plug on 5-1/2" casing stub.
5. Spot 50 sack cement plug at 5400' if not cased off.
6. Spot 50 sack cement plug at base of 8-5/8" casing at 4200'.
7. Recover 8-5/8" casing. Set at 4200'. Top of cement @ 2400'.
8. Spot 50 sack cement plug at 8-5/8" casing stub.
9. Spot 100 sack cement plug at 11-3/4" casing shoe at 400'.
10. Fill top of 11-3/4" casing with concrete, weld on steel plate and install marker.

⑪ spot 100' plug at top of Abo @ 7682', if not behind pipe.
⑫ spot 100' plug at top of Glorieta @ 5140'

Exposure 9/5/77

xc: OCC (3), WNM, JVL, FILE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED P.R. Blumenthal TITLE Operations Engineer DATE 9-8-76

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: