Form 9-331 (May 1963)			5. LEASE DESIGNATION AND BERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)			G. IP INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL GAS WELL OTHER SI Well 2. NAME OF OPERATOR			7. UNIT AGHEEMENT NAME
Tenneco Oil Company			8. FARM OR LEASE NAME
3. ADDRESS OF OPERAT	on company	Anderson Federal Com.	
1860 Lincoln St., Suite 1200, Denver, Co. 80203			9. WELL NO. #1
4. LOCATION OF WELL (See also space 17 be At surface	(Report location clearly and in accordance with an elow.)	y State requirements.*	# 1 10. FIELD AND POOL, OR WILDCAT
1980' FSL and 1980' FEL			Vada Penn 11. BEC., T., R., M., OB ELK. AND BURVEY OR ARDA
14. PERMIT NO.	15 FLEVATIONS (Shows Lat		Sec. 9, T9S, R35E
	15. ELEVATIONS (Show whether D 4179' KB	P, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
16.			Lea New Mexico
	Check Appropriate Box To Indicate 1	Nature of Notice, Report, or	Other Data
TEST WATER SHUT-(SUBSEC	QUANT REPORT OF:
FRACTURE TREAT	DFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
SHOOT OR ACIDIZE	ABANDON* XX	SHOOTING OR ACIDIZING	ALTERING CASING
REPAIR WELL	CHANGE PLANS	(Other)	ABANDONMENT*
(Other) 17. BESCRIBE PROPOSED O	R COMPLETED OPERATIONS (Clearly state all pertinen f well is directionally drilled, give subsurface loca	(NOTE: Report result Completion or Recomp	s of multiple completion on Well Diction Report and Log form.)
PRESENT CO and CIBP @ Cement top uneconomic We propose 1. MIRUPU 2. Freepo zone, spot casing. 3. GIH w/ 4. Freepo Spot 75 sac 5. GIH w/ 6. Cut off level all p	NDITION: Plugback operation in 8775' w/30' of cement on top. 04810 behind 5-1/2" csg and g al. Squeezed perfsw/35 sacks to plug and abandon this well , GIH w/tubing to PBTD 0 4750, int 5-1/2" csg. and shoot off 35 sacks across 5-1/2" csg. tubing to 2350', spot 50 sack int and shoot off 8-5/8" csg. cks across 8-5/8" csg. stub wi tubing to -430, spot 75 sacks f wellhead, set a 10 sack surf pits, and clean up area of all agency specifications.	in 1975 with a CIBP @ 200 sacks of cemen 5020' inside 5-1/2" c of cement. New cemen as follows: spot 25 sacks from 4 as low as possible. stub with tubing. P(s in 8-5/8" csg. from as low as possible. th tubing. POH w/tut across 13-3/8 shoe f ace plug and install debris. We will res	9747' w/30' of cement on top t behind 5-1/2" csg. @5032'. sg. Perf'd, swabbed.but was nt top @4750'. 4750' - 4550'. POH. Pull 5-1/2" csg. above DH w/tubing. POH w/5-1/2" n 2350' - 2200'. POH Pull 8-5/8" above zone. oing. POH w/8-578" csg. from 430 to 330. POH. dry hole marker, fill and seed location as per
		SEE ATTACHED FOI	R NAL
SIGNED		v. Production Manager	- DATE - / Les
(This space for Federa	il or State office use)		
APPROVED BY CONDITIONS OF APP		APPROVE AS AMENE C. OCT 22 197	E BARE
	See manuements (AS AMERICA OF Reverse Side ARTHUR R. BE DISTRICT ENG	AINEER

ų T

RECEIVED

HO 2 1976 OIL CONSERVATION COMM. HOBBS, N. M. U. S. Geological Survey P. O. Box 1157 Hobbs, New Mexico

HOBBS DISTRICT

Operator: Tenneco Oil Co.

Well: No. 1 Anderson Federal Com.

Lease No. New Mexico 0149818

CONDITIONS OF APPROVAL

- Plugging operations authorized are subject to the attached "General 1. Requirements for Permanent Abandonment of Wells on Federal Leases".
- The Hobbs office (telephone (505) 393-3612) is to be notified in 2. sufficient time for a representative to witness all plugging operations.
- 3. Blowout prevention equipment is required.
- 4. In addition to normal filling of pits and cleanup of location, additional surface restoration work <u>may</u> be required, i.e., ripping of pad and/or access road, reseeding, etc. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
- 5. Cement plug at top of $5\frac{1}{2}$ " casing stub should be 50 sacks rather than

RECEIVED

OIL CONSERVATION COMM. HOBBS, N. M.

.