

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <i>Tenneco Oil Company</i>	8. Farm or Lease Name <i>Barton-Santa Fe</i>
3. Address of Operator <i>Box 1031 Midland 79701</i>	9. Well No. <i>1</i>
4. Location of Well UNIT LETTER <i>L</i> , <i>1980</i> FEET FROM THE <i>South</i> LINE AND <i>660</i> FEET FROM THE <i>West</i> LINE, SECTION <i>10</i> TOWNSHIP <i>9S</i> RANGE <i>36 E</i> NMPM.	10. Field and Pool, or Wildcat <i>Vada (Penna)</i>
15. Elevation (Show whether DF, RT, GR, etc.) <i>406.4 GR</i>	12. County <i>Lea</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

*To continue P&A operations reported on C-103 dated approval 8-31-70  
12-1-70*

- 1. Cut and recover 8 5/8" casing from 1000' ±.*
- 2. Set a 25 sx plug across 8 5/8" casing stub.*
- 3. Set a 25 sx plug across 13 3/8" shoe @ 356'*
- 4. Set a 25 sx plug at surface.*
- 5. Erect Dry Hole marker.*
- 6. Clean location.*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *L. M. Williams* TITLE *Prod Engr* DATE *11-23-70*

APPROVED BY *[Signature]* TITLE *STATIONER DISTRICT 1* DATE *11-23-70*

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 24 1979  
ON CONSERVATION  
BUREAU OF LAND MANAGEMENT