Submit 3 Copies to Appropriate

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office			4										
DISTRICT I	OIL CONSERVA			WELL API NO.	· · · · · · · · · · · · · · · · · · ·								
P.O. Box 1980, Hobbs NM 88241-1980 2040 Pacheco St.				30-02 <i>5</i>- 23728									
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				5. Indicate Type of Lease STATE THE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name									
							1. Type of Well:				Henry		
							OIL XX GAS WELL	OTHER					1
							2. Name of Operator				8. Well No.	1	
							Enron 011 & Gas Company					1	
3. Address of Operator				9. Pool name or Wildcat									
P.O. Box 2267 Midland, TX	79702			Vada (Penn)									
4. Well Location				_									
Unit Letter A: 660	Feet From The North	1	Line and66(Feet Fron	n The <u>East</u>	_ Line							
_	093	_	a E r	\n. co. (100 0								
Section 5	Township 195		nge 35E r DF, RKB, RT, GR, et	NMPM	Lea c	ounty							
	//////	4:	199 GR										
11. Check An	propriate Box to Ind	icate l	Nature of Notice.	Report, or C	ther Data								
-	NTENTION TO:	icuto i	1	<u>-</u> .	REPORT OF:								
NOTICE OF IN	HENTION TO.		30.	DOLGOLINI	ILLI OILI OI .								
PERFORM REMEDIAL WORK	PLUG AND ABANDON	\mathbf{x}	REMEDIAL WORK		ALTERING CASING								
TEMPORARILY ABANDON LI CHANGE PLANS LI COMMENCE DRIL				GOPNS.	PLUG AND ABANDONME	NT L							
PULL OR ALTER CASING			CASING TEST AND CEMENT JOB										
OTHER:			OTHER:			🗆							
12. Describe Proposed or Completed Ope work) SEE RULE 1103.	rations (Clearly state all perti	nent deta	ils, and give pertinent da	ates, including estima	ated date of starting any pr	oposed							
,													
2)Back off and pu 3)Set 100' cement from 7950' to 8 4)Set 100' cement 5)Set cement plug plug with tubin 6)Set 60' cement	o' + 35' of cement all approximately 8 plug across 4-1/2 8050'. Tag cement p plug from 5950' to from 3966' to 406 g. plug from surface e marker. Clean a	3000' 2" ca: olug v to 60! to 6!	of 4-1/2" cassing stub. 50' with tubing. 50'. 50' in and 50	in and 50' ' out of 8-5									
See attached well	diagram.												
I hereby certify that the information above is tr	ne and complete to the best of my k			•	10/17/00								
SIGNATURE 4. / SI	rich.	_ TITL	Engineer Te		DATE 12/17/99								
TYPE OR PRINT NAME M. Lee Roar	·k				тецерноме но. 915/686-	<u>-/3608</u>							
(This space for State Use) OFFIC NAT ST	DAJED OK DRIBIR MILLIA	Ms											
UST	THE RESERVATION		_		_ :								