

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ For ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Firm or Lease Name Pruitt "B"
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 2
4. Location of Well UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 18 TOWNSHIP 9-S RANGE 34-E N.M.P.M.	10. Field and Pool, or wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4311.6' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon well as follows:

Move in service unit. Pull rods and pump. Pull tubing anchor and tubing. Run in hole with CIBP. Test to 500 PSI. Cap with 35' of cement. Run freepoint and cut 5½" casing 100' above freepoint. Pull 5½" casing. Spot 50 sack cement plug across the 5½" casing stub. Pull up and spot a 25 sack cement plug across the 8-5/8" casing shoe at 3955'. Run freepoint survey and cut 8-5/8" casing 100' above freepoint. Pull 8-5/8" casing. Spot a 5 sack cement plug across the 8-5/8" casing stub. Pull up and spot a 50 sack cement plug across the 12-3/4" casing shoe at 320'. Spot a 10 sack surface plug. Weld on cap and erect PXA marker. (Spot plugging mud between all plugs.)

0+5-NMOCD,H 1-HOU 1-DMF 1-W. Stafford, HOU

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark Freeman TITLE Assist. Admin. Analyst DATE 12-17-82

APPROVED BY ORIGINAL SIGNED BY
JERRY SEXTON
CONDITIONS OF APPROVAL, IF ANY
DISTRICT 1 SUPR.

TITLE

DEC 21 1982