

3 Copies
appropriate
Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

RICT I
Box 1980, Hobbs, NM 88240

RICT II
Drawer DD, Artesia, NM 88210

RICT III
000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025 23898
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	002089
7. Lease Name or Unit Agreement Name	
Gray	
8. Well No.	1
9. Pool name or Wildcat	Vada Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Floyd Operating Company	3. Address of Operator 777 Walker, Suite 2400 Houston, Texas 77002
4. Well Location Unit Letter C : 660 Feet From The North Line and 3300 Feet From The East Line Section 18 Township 09S Range 34E NMPM Lea County		
10. Elevation (Show whether DP, RKB, RT, GR, etc.) 4315.7 GL		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. PROCEDURE: Start on P&A as soon as approval received.

- MIRU - POOH W/rods & tubing
- Set CIBP @9600' - dump 3 sxs on top RIH w/workstring
- cir. 9.5# mud
- pull 5 1/2" casing from 5000'±
- spot 45 sxs @stub & tag
- spot 45 sxs @4016'-3916' & tag
- spot 35 sxs @2000'-1900' top of salt
- pull 8 5/8" casing @ 400'±
- spot 65 sxs @450'-325' TAG
- spot 15 sxs @Surface
- cut off wellhead & anchors-cover pit-move out

(If dump boiler is used 35' of Cem)
14 pmpd. through TAG 25sxs

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Leah Moon Becton TITLE Production Administrator DATE 3-8-99
TYPE OR PRINT NAME Leah Moon Becton TELEPHONE NO (713) 222-6275

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: