STATE OF NEW MEXICO NERGY AND MINERALS DEPARTMENT	Form C-103 Revised 10-1 -7 8
NO. OF COPIES RECEIVED OIL CONSERVATION DIVISION	11641360 10 1 70
DISTRIBUTION P.O. Box 2088	5a. Indicate Type of Lease
SANTA FE, NEW MEXICO 87501	State Fee X
FILE	+
U.S.G.S LAND OFFICE	5. State Oil & Gas Lease No.
OPERATOR OPERATOR	-
SUNDRY NOTICES AND REPORTS ON WELLS	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
(DO NOT USE THIS FORM FOR PROPUSALS TO DRILL OR TO DEEL EN OR TEOD BROKE TO A STITLEMENT	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SOCIETY	7. Unit Agreement Name
OIL GAS WELL OTHER Dry Hole	
WELL	8. Farm or Lease Name
Name of Operator	Sheridan "Com"
Read & Stevens, Inc. Address of Operator	9. Well No.
P.O. Box 1518, Roswell, NM 88201	1
. Location of Well	10. Field and Pool, or Wildcat
THE MALE AND SEA SECT FROM	Vada Penn
UNIT LETTER D . 554 FEET FROM THE North LINE AND 554 FEET FROM	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
THE West LINE. SECTION 19 TOWNSHIP 9S RANGE 34E NMPM	<u> </u>
:xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx	12. County XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
Check Appropriate Box To Indicate Nature of Notice, Report or Other NOTICE OF INTENTION TO: SUBSEQUENT RE	PORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING CASING TEST AND CEMENT JOB	
OTHER OTHER	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
escribe Proposed or Completed Operations(Clearly state all pertinent details, and give ated date of starting any proposed work) SEE RULE 1103.	perfinent dares, including esti-
1) Set CIBP w/30' cmt @ 9600'. Circulate hole w/mud.	Commence of the state of the st
2) Spot 25sx cmt 8900'-8700'.	
3) Cut csg @ <u>+</u> 6000', pull csg, TOC @ 6520.	FNDV FD
4) Spot 40sx cmt plug half in & half out of csg stub 6100'-5900'.	
5) Spot 35sx cmt plug 5300'-5200'.	
6) Spot 40sx half in & half out of 8 5/8" csg set @ 3945', 4050'-	-3850'.
7) Cut 8 5/8" csg off @ 1000", pull csg.	
8) Spot 50sx cmt plug, half in & half out of 8 5/8" csg stub, 110	00'-900'.
9) Spot 65sx cmt plug across 13 3/8" csg shoe @ 349', 400'-300'.	
10) Spot 10sx cmt plug @ surface w/4"X10' Dry Hole marker.	
11) Clean up location prep for Inspection.	
I hereby certify that the information above is true and complete to the best of my known	owledge and belief.
SIGNED Aublo TITLE Drilling & Production Manage	er DATE 11-29-82
ORIGINAL SIGNED BY	DEC 3 1982
APPROVED BY JERRY SEXTON TITLE	DATE DEC 3 1302

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY_

DISTRICT 1 SUPR.