

ATTACHMENT TO FORM C-103
SUNDRY NOTICES AND REPORTS ON WELLS

- e. 100' plug 50' in and 50' out of 8-5/8" casing stub.
 - f. 100' plug 1700'-1800' (top of salt 1840')
 - g. 100' plug 330'-430' across 13-5/8" casing shoe -
50' in and 50' out of casing.
 - h. 10 sack plug at surface.
5. Install permanent surface marker and clean location.