

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-7481

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Bridwell Oil Company	8. Farm or Lease Name N.M. 7LL State
3. Address of Operator P. O. Box 2038, Abilene, Texas 79604	9. Well No. 2
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>East</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>7</u> TOWNSHIP <u>9-S</u> RANGE <u>33E</u> N.M.P.M.	10. Field and Pool, or Wildcat Flying "M"-San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4394 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug & Abandonment Operation 7-23-80 thru 7-29-80

7-23-80 MIRU DA&S Rig #832 Pull Rods
7-24-80 Pull tubing. Set CIBP @ 4350 w/35' cement on Top, Circulated Hole w/10.2ppg mud.
7-25-80 Free Pointed Casing @ 1100'. Tried 3 times to shoot casing off. Pulled pipe into on last shot. Pulled casing.
7-26-80 Ran tubing Spotted plug @ 1900' & 1150', 75sx each. Pull tubing.
7-28-80 Tagged plug @ 1050'. Spotted 75 sx Plug @ 416'
7-29-80 Tagged plug @ 385' Spotted 35 sx Plug. Pulled tubing. Spotted 15 sx plug in top w/ dry hole marker. Cleaned up location. R.D.M.O.
Pits filled. Location leveled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mike Lafford TITLE Prod. Supt. DATE 9-2-80

APPROVED BY A.H. Statton TITLE OIL & GAS INSPECTOR DATE SEP 4 1980

CONDITIONS OF APPROVAL, IF ANY: