(May 1963)	DEPARTM		TERIOR	SUBMIT IN TRIPLICA (Other instructions (verse side)		Form approved. Budget Bureau No. 42-R142 ASE DESIGNATION AND SERIAL NO. LC - 067775
<u> </u>	Gi	EOLOGICAL SURV	LY		<u>6 10</u>	ILC - UO / / / D
		CES AND REPO			0. 1	INDIAN, ALLOTTEE OR TRIBE NAM
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)						
1.	-		····		7. UN	IT AGREEMENT NAME
WELL X GAS WELL	OTHER					
2. NAME OF OPERATOR					8. FA	BM OR LEASE NAME
John L.	Cox					U. S. M.'
3. ADDRESS OF OPERATOR					9. wi	ELL NO.
408 West Wall, Midland, Texas 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*						<u>3: A 2, A (3) A (4) Q (4)</u>
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 					1	IELD AND POOL, OR WILDCAT
519' FNL, 801 FEL					<u>W.</u>	Sawyer (San Andr
					11. 5	EC., T., B., M., OB BLK. AND SUBVEY OR ABEA
						27, 9S, 37E
14. PERMIT NO.		15. ELEVATIONS (Show wh	ether DF. RT. GR.	etc.)		OUNTY OF PARISH 13. STATE
		3963.4				
				. <u></u>		Lea New Mex
16.	Check App	propriate Box To Indi	cate Nature	of Notice, Report, c	or Other [Data di 1 di 1 di 1 di 1
NO	TICE OF INTENT	ION TO:	1	SUB	SEQUENT RE	PORT OF:
TEST WATER SHUT-OFF	PO	ILL OR ALTER CASING		WATER SHUT-OFF		BEPAIRING WELL
FRACTURE TREAT		ULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASING
SHOOT OR ACIDIZE	AB	BANDON*		SHOOTING OR ACIDIZING	·	ABANDONMENT*
REPAIR WELL	сн	IANGE PLANS		(Other) Running	8 5/8	" casing X
(Other)				(NOTE: Report res	ults of mul	tiple completion on Well eport and Log form.)
5/8" casing,	20# set		325 sx	. Class H cer		vith 2% c alcium
5/8" casing, hloride. Circ	20# set	@ 413' with	325 sx	. Class H cer		vith 2% c alcium
5/8" casing, hloride. Circ TOC 24 hrs.	20# set culated	@ 413' with 50 sx. Plug	325 sx down l	. Class H cen :30 a.m. 1-1		vith 2% c alcium
5/8" casing, hloride. Circ OC 24 hrs. ressure tested	20# set culated d casing	@ 413' with 50 sx. Plug to 1000# fo:	325 sx down l	. Class H cen :30 a.m. 1-1	1-74.	vith 2% c alcium
5/8" casing, hloride. Circ OC 24 hrs. ressure tested	20# set culated d casing	@ 413' with 50 sx. Plug to 1000# fo:	325 sx down l	. Class H cen :30 a.m. 1-1	1-74.	tith 2% c alcium
5/8" casing, hloride. Circ OC 24 hrs. ressure tested	20# set culated d casing	@ 413' with 50 sx. Plug to 1000# fo:	325 sx down l	. Class H cen :30 a.m. 1-1	1-74.	<pre>ith 2% c alcium but in a probability in the pro- but in the in the pro- to pro- to</pre>
5/8" casing, hloride. Circ OC 24 hrs. ressure tested	20# set culated d casing	@ 413' with 50 sx. Plug to 1000# fo:	325 sx down l	. Class H cen :30 a.m. 1-1	1-74.	<pre>inter a construction of a local sector of a</pre>
5/8" casing, hloride. Circ OC 24 hrs. ressure tested	20# set culated d casing	@ 413' with 50 sx. Plug to 1000# fo:	325 sx down l	. Class H cen :30 a.m. 1-1	1-74.	<pre>Addition of the control of the second s</pre>
5/8" casing, hloride. Circ OC 24 hrs. ressure tested	20# set culated d casing	@ 413' with 50 sx. Plug to 1000# fo:	325 sx down l	. Class H cen :30 a.m. 1-1	1-74.	Ar the bar of the state of the
5/8" casing, hloride. Circ OC 24 hrs. ressure tested	20# set culated d casing	@ 413' with 50 sx. Plug to 1000# fo:	325 sx down l	. Class H cen :30 a.m. 1-1	1-74.	<pre>A set state has set a second set set set set set set set set set set</pre>
5/8" casing, hloride. Circ OC 24 hrs. ressure tested	20# set culated d casing	@ 413' with 50 sx. Plug to 1000# fo:	325 sx down l	. Class H cen :30 a.m. 1-1	1-74.	<pre>is a first a state of a construction of the state of</pre>
5/8" casing, hloride. Circ OC 24 hrs. ressure tested	20# set culated d casing	@ 413' with 50 sx. Plug to 1000# fo:	325 sx down l	. Class H cen :30 a.m. 1-1	1-74.	<pre>A the problem of the contract of the problem o</pre>
5/8" casing, hloride. Circ OC 24 hrs. ressure tested	20# set culated d casing	@ 413' with 50 sx. Plug to 1000# fo:	325 sx down l	. Class H cen :30 a.m. 1-1	1-74.	
5/8" casing, hloride. Circ OC 24 hrs. ressure tested	20# set culated d casing	@ 413' with 50 sx. Plug to 1000# fo:	325 sx down l	. Class H cen :30 a.m. 1-1	1-74.	<pre>A second for the fact that we shall not set the second set of the second second second set of the second secon</pre>
5/8" casing, hloride. Circ OC 24 hrs. ressure tested rilling ahead	20# set culated d casing in 7 7/	@ 413' with 50 sx. Plug to 1000# fo: 8" hole.	325 sx down l	. Class H cen :30 a.m. 1-1	1-74.	An even the state of the set of t
5/8" casing, hloride. Circ OC 24 hrs. ressure testec rilling ahead	20# set culated d casing in 7 7/	@ 413' with 50 sx. Plug to 1000# fo: 8" hole.	325 sx down 1 r 30 min	. Class H cen :30 a.m. 1-1 nutes. Test	0kay.	(a) A second proper generation does be a metal of an external second
5/8" casing, hloride. Circ OC 24 hrs. ressure tested rilling ahead	20# set culated d casing in 7 7/	<pre>@ 413' with 50 sx. Plug to 1000# fo: 8" hole. </pre>	325 sx down 1 r 30 min	Class H cer	0kay.	
 5/8" casing, hloride. Circle OC 24 hrs. ressure tested orilling ahead 18. I hereby certify that the SIGNED Area 	20# set culated d casing in 7 7/	<pre>@ 413' with 50 sx. Plug to 1000# for 8" hole. Pue and correct Wittenbach TITLI Wittenbach</pre>	325 sx down 1 r 30 min	Class H cer	0kay.	
18. I hereby cerbby that the	20# set culated d casing in 7 7/	<pre>@ 413' with 50 sx. Plug to 1000# for 8" hole. Pue and correct Wittenbach TITLI Wittenbach</pre>	325 sx down 1 r 30 min	Class H cer 30 a.m. 1-1 nutes. Test	okay.	
 5/8" casing, hloride. Circle OC 24 hrs. ressure tested orilling ahead 18. I hereby certify that the SIGNED	20# set culated d casing in 7 7/ in 7 7/ he foregoing is the Martha i or State office	<pre>@ 413' with 50 sx. Plug to 1000# fo: 8" hole. Pue and correct Wittenbach use) TITLI</pre>	325 sx down 1 r 30 min	Class H cer 30 a.m. 1-1 nutes. Test	okay.	
 5/8" casing, Theoride. Circle 70C 24 hrs. ressure tested orilling ahead 18. I hereby certhy that the SIGNED Management (This space for Federal) 	20# set culated d casing in 7 7/ in 7 7/ he foregoing is the Martha i or State office	<pre>@ 413' with 50 sx. Plug to 1000# fo: 8" hole. Pug and correct</pre>	325 sx down 1 r 30 min	ACCEPTED FOR	okay.	
 5/8" casing, Circle Circle C 24 hrs. ressure tested ressure tested rilling ahead 18. I bereby certity that the SIGNED	20# set culated d casing in 7 7/ in 7 7/ he foregoing is the Martha i or State office	<pre>@ 413' with 50 sx. Plug to 1000# fo: 8" hole. Pug and correct</pre>	325 sx down 1 r 30 min	ACCEPTED FOR	okay.	
 5/8" casing, Circle Circle C 24 hrs. ressure tested ressure tested rilling ahead 18. I bereby certity that the SIGNED	20# set culated d casing in 7 7/ in 7 7/ he foregoing is the Martha i or State office	<pre>@ 413' with 50 sx. Plug to 1000# fo: 8" hole. Pug and correct</pre>	325 sx down 1 r 30 min	ACCEPTED FOR	okay.	
5/8" casing, hloride. Circ OC 24 hrs. ressure tested rilling ahead 18. I bereby certhy that th SIGNED Manual (This space for Federal APPROVED BY	20# set culated d casing in 7 7/ in 7 7/ he foregoing is the Martha i or State office	<pre>@ 413' with 50 sx. Plug to 1000# fo: 8" hole. Pug and correct</pre>	325 sx down 1 r 30 min	Class H cer 30 a.m. 1-1 nutes. Test	okay.	

•'